REMINGTON ARMS COMPANY, INC. Firearms Research Division

January 18, 1982

TO:

C. B. WORKMAN

FROM:

C. E. RITCHIE

EVALUATION OF LUBRICANTS ON FIREARMS

# ABSTRACT

Remington Arms Company is interested in developing a cleaning and lubrication procedure for the Model 700 Fire Control that can be included in the rifles instruction manual. It is intended the cleaning and lubrication procedure be done without disassembly from the receiver and the products used should not gum up the close tolerances of the mechanism. The products selected should also be readily available on a nationwide basis, be non-flammable and non-toxic, as well as operate from -20°F to 120°F.

Preliminary evaluations were conducted by A.B. Hughes, Senior Consultant, ESD Maintenance Engineering Group, with conclusions reported on August 24, 1981 in document entitled "Maintenance Engineering - Lubrication of Rifles". Twenty-five (25) products were finally screened for rust removal, rust prevention, grease displacement, water displacement, cleaning capability, and appearance on metal and wood firearms parts. From this evaluation five candidates have been recommended for further testing:

- Du Pont Synthetic Diesther
- Krylon Ten-4
- 3. Sprayon 711
- 4. CRC 3-36
- 5. Houghton HLP

These five lubricants (along with 2 lubricants presently being used in Firearms Research Test Lab - WD-40 and Molycote GN-paste) will now be subjected to a more extensive test which best duplicates conditions the rifle will experience in the field and storage between hunting seasons.

(All to fake place

in one day

SCOPE OF NEW TESTS

\_M , 3

List of lubricants to be tested:

- Dry Condition (No lubricant) Du Pont Synthetic Diesther
- Krylon Ten-4
- Sprayon 711
- CRC 3-36
- Houghton HLP
- WD-40 > R&D Ilion results only Molycote GN-paste

Tests to be conducted will include:

- Cock & Fire Dry cycle tests
- Environmental/Cold Tests
- Cleaning Capability, Rust Removal & Prevention Analysis

-2-

#### Sample size:

1 - M/700 Rifle, 5 bolts, 5 fire controls per lubricant and controls.

# Environmental/Cold Tests

#### Firearms:

M/700 and M/1100

- 1. Photos of surfaces where lubricant applied.
- 2. Determine application (same as dry cycle tests)
- 3. Live round jack shooting in following sequence:
  - Take bolt and closing velocities, fire 100 rounds,
  - Place firearm on roof of building for 4 hours
  - Place firearm in freezer for remainder of shift (specify time on log) at  $-20^{\circ}F$ .
  - Place rifle in stress coat oven overnight at +120°F.
- 4. Continue with Step 3 for one week or until failure of firearm to function properly occurs.

1-18-82

# "Failure to Function Properly"

- The firearm does not perform as designed. 0
- О Evaluate rust development if any.
- Record the function of the M/1100 via bolt velocities and/or closing velocities during test every 100 rounds.
- Observe safety operation on both firearms during test.

# Cock & Fire Dry Cycle Test Procedure

- 1. Photos at start of test
  - Cocking cam surface on bolt body
  - Firing pin striker
- 2. Apply lube:

a.

Determine amount of spray

Bolt assembly

(1 sec./2 sec., distance from

- see left / see enzagement

surface, etc.)

- Fire control assembly
- 3. Take the following measurements:
  - Trigger pull
  - Safe on/off forces

Bolt life -- cocked & fired

4. Start Dry Cycle

0, every 100 cycles on 1st sample of each Inspection cycles:

lube to determine inspection cycle for

remaining four samples.

Monitor cycles:

6. Measurements: (#3)

Auto counter and human inspection.

5. Cycle Limit:

25,000 cycles all samples - or failure. Re-evaluate at 25,000 cycles if failure does

will be taken on samples #2 thru #5 at levels

not occur.

- determined by sample #1.
- 7. Photos at completion of test or failure
  - Cam track area on bolt
  - Firing pin striker area b.
  - Sear and connector surfaces of fire control



8. Measurements (#3) taken at completion of test.

Note: Two dry cycle machines available.

Cycle rate: 1 every 3 seconds per machine.

# Cleaning Capability, Rust Removal & Prevention Analysis

Firearms: Consignment guns at Ilion Fish & Game Club (Winter Skeet/Trap Shooting)

(All firearms tested will be M/1100 - 12 & 20 Ga.)

- Review firearms and select for excessive crud/dirty condition and rust evident on surfaces of receiver and barrel.
- 2. Assign a lubricant to a firearm.
- 3. Record via photos; crud and rust.
- Attempt to clean firearm using assigned lubricant and document results.
- 5. Thoroughly clean firearm by other means if assigned lubricant fails to do so.
- 6. Lubricate firearm with assigned lubricant.
- Maintain accurate log on each firearm in test for one month's usage at the Gun Club, or longer depending on results.
  - o Date rounds fired
  - o Load used
  - o Shooters comments on function
  - o Weather
  - o Storage location and temperature variance.
- 8. Review condition of firearms and record results of crud and rust via photos.

Note: Bolt velocities at start and finish?

CER · T

Test., Meas.& Mech. Analysis Lab



Objectives to SEG. ABOUT DEVELOPMENT (BY REMINICION) Jan 1982 Remir str is looking for a lubrican funt won't "jum of the Fire control.

They intend to discribe the cleaning and lubing procedure in The processing REMINGTON ARMS COMPANY, INC. Firearms Research Division

> January 18, .1982 -

V. 12

#### ABSTRACT

Remington Arms Company is interested in developing a clearing and lubrication procedure for the Model 700 First Control that can be included in the risles instruction manual white spin and the relation in the risles instruction manual white spin and the relation in the result of the risles in the result in the result is the result of the result in the result in the result in the result is products used should not good up the close tolerances of the result in the products selected should also be readily available on a nationwide basis, be non-flammable and non-toxic, as well as operate from -20 F to 120 F.

Preliminary evaluations were conducted by A.B. Bughes, Semior Consultant, ESD Maintenance Engineering Group, with conclusions reported on August 24, 1981 in document entitled "Maintenance reported on August 24, 1981 in document entitled "Maintenance Engineering - Lubrication of Rifles". Twenty-five (25) products were finally screened for rust removal, rust prevention, grease displacement, water displacement, cleaning capability, and appearance on metal and wood firearms parts. From this evaluation five candidates have been recommended for further testing:

- Du Pont Synthetic Diesther Krylon Ten-4
- Krylon Ten-4 Sprayon 711 2.
- З.
- Eoughton ELP

These five lubricants (along with 2 lubricants presently being used in Firezons Research Test Lab - WD-40 and Molycote GN-paste) will now be subjected to a more extensive test which best duplicates conditions the rifle will experience in the field and storage between hunting seasons.

Eake place in one day

### SCOPE OF NEW TESTS

List of lubricants to be tested:

- Dry Condition (No lubricant) Du Pont Synthetic Diesther
- - Krylon Ten-4
  - Sprayon 711
- CRC 3-36
- Edughton ELP
  - ₩D-40 Molycote GN-paste

Tests to be conducted will include:

- Cock & Fire Dry cycle tests
- Environmental/Cold Tests
  - Cleaning Capability, Rust Removal & Prevention Analysis

Sample size:

- M/700 Rifle, 5 bolts, 5 fire controls per lubricant and controls.

# Environmental/Cold Tests

M/700 and M/1100

- Photos of surfaces where lubricant applied.
- Determine application (same as dry cycle tests)
- 3. Live round jack shooting in following sequence:
  - Take bolt and closing velocities, fire 100 rounds,
  - Place firearm on roof of building for 4 hours
  - Place firearm in freezer for remainder of shift (specify time on log) at -20 F.
  - Place rifle in stress coat oven oversight at +120°F.
- Continue with Step 3 for one week or until failure of firearm to function properly occurs.

# "Failure to Function Properly"

- The firezrm does not perform as designed.
- Evaluate rust development if any.
- Record the function of the M/lloo via bolt velocities and/or closing velocities during test avery 100 rounds.

  Observe safety operation on both firefres during test.

# Cock & Fire Dry Cycle Test Procedure

- 1. Photos at start of test
  - Cocking cam surface on bolt body
  - Firing pin striker
- 2. Apply lube:

Determine amount of spray

(1 sec./2 sec., distance from

- Fire control assembly b.
- Trigger pull (3)
- Safe on/off forces (3)

Take the following measurements:

- Bolt list cocked & fired

Start Dry Cycle

Inspection cycles: 0, every 100 cycles on 1st sample of each
lube to determine inspection cycle for - zeneining four samples.

Monitor cycles: Auto counter and human inspection.

- Limit: 25,000 cycles all samples or failure.

  Re-evaluate at 25,000 cycles if failure does
  not occur.
- Measurements: (#3) will be taken on samples #2 thru #5 at levels determined by sample #1.
- 7. Photos at completion of test or failure
  - Cam track area on bolt
  - Piring pin striker area b.
  - Sear and connector surfaces of fire control

er Tu

5 7. •

8. Measurements (#3) taken at completion of test.

Note: Two cry cycle machines available.

Cycle rate: 1 every 3 seconds per machine.

# Cleaning Capability, Rust Removal & Prevention Analysis

Firearms: Consignment guns at Ilion Fish & Game Club
(Winter Skeet/Trap Shooting)

"(All firearms tested will be M/1100 - 12 £ 20 Ga.)

- Review firearms and select for excessive crud/dirty condition and rust evident on surfaces of receiver and berrel.
- 2. Assign a lubricant to a firearm.
- 3. Record via photos; crud and rust.
- 4. Attempt to clean firearm using assigned lubricant and document results.
- 5. Thoroughly clean firearm by other means if assigned lubricant fails to do so.
- 6. Lubricate firearm with assigned lubricant.
- Maintain accurate log on each firearm in test for one month's usage at the Gun Club, or longer depending on results.
  - o Date rounds fired
  - o Load used
  - o Shooters comments on function
  - o Weather
  - o Storage location and temperature variance.
- 8. Review condition of firearms and record results of crud and rust via photos.

Note: Bolt velocities at start and finish?

Test., Meas. & Mech. Analysis Lab