

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-02836

INITIAL CUSTOMER ORDER NO.

CALL TAG ATTN: DENNIS SANITA

DATE RECEIVED 11/21/94	DATE OPENED 01/24/94	DATE CODE LH 2-87	SERIAL NUMBER B6847096	NEW SERIAL NUMBER	MODEL AND GRADE 700 243 WIN ADL
ACCESSORIES W/STUDS					

FROM:

BROWN, DEE M.
RT 5 BOX E-29
VILLE PLATTE

LA 70586

SHIP TO:

BROWN, DEE M.
RT 5 BOX E-29
VILLE PLATTE

LA
70586

CUST NO: 091118 C.O.D L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

U59001

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

BUN CONDITION

- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
------------------	------	----------	--------	----------	-----	---------

CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5			E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Unable to duplicate customer concern. Examination revealed that the rifle needs a good cleaning, bolt body dirty, and more than normal force required to move bolt body assembly.

ARTS

COMMENTS

Customer requests we change to M/200 pump in 243 Win.
Agreed to change, no question of price.

Supply replacement M/200 243 Cal (4653)
New #

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

Replac TAON M200 sent to WIP OFFICE COPY

RD6925 REV 1/92