

# RECEIVING AND ESTIMATING REPORT

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS ATTN K GREEN			
DATE RECEIVED 10/30/90	DATE OPENED 10/31/90	DATE CODE PI 6-88	SERIAL NUMBER C6265415	MODEL AND GRADE 700 7MMAG	BDL	ORDER 90-2865	R
ACCESSORIES W/STUDS							

FROM:

BURNS, JOHNNY  
3336 COUNTRY CLUB DR  
CHARLOTTE NC 28205

SHIP TO:

BURNS, JOHNNY  
3336 COUNTRY CLUB DR  
CHARLOTTE NC  
28205

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

J. P. FOSTER  
5018 CAXILION DR.  
CHARLOTTE, NC 28226

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
GUN CONDITION: <input checked="" type="checkbox"/> LIKE NEW <input type="checkbox"/> SLIGHTLY WORN <input type="checkbox"/> VERY WORN <input type="checkbox"/> MISUSED <input type="checkbox"/> MARRED					
CUSTOMER'S REQUEST					

"GUN FIRED WHEN SAFETY WAS PUSHED OFF"

MAIN FAULT: Trigger assembly rusted from unknown source. Internal parts not moving properly.

Note: barrel rusty at pressure point location and, rear guard assembly rusty. Appears rifle was wet at some time & not properly maintained.

PARTS: Per J. Foster (Sales Rep) instructions, rifle to be return shipped to him via U.P.S. NEXT DAY

Replace Trigger assembly at no-charge, in gesture of good-will

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 7/9

PPS 00791