

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 94-02651

INITIAL

CUSTOMER ORDER NO.

JUM

Product Service

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

01/20/94

01/20/94

OH 7-87

B6878895

700 7MMAG

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/REAR SIGHT

FROM:

SHIP TO:

CAMPORESE, ANTHONY
88-24 69TH AVE
FOREST HILLS

NY 11375

CAMPORESE, ANTHONY
88-24 69TH AVE
FOREST HILLS

NY

11375

CUST NO: 091039 C.T.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

059001

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

D2

BOLT ASSY.

B3

BARREL ASSY.

E4

REC. ASSY.

B5

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

Unable to disassemble custom concern of the rifle firing
when pushing to safety to its off position. However, more than
normal force is required to move safety. Action & trigger moving
with a heavy amount of a gunning substance. Rifle needs a good clean
Just found on bottom of receiver.

COMMENTS

Replace trigger spring
& clean action at the change

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/8