RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL	CUSTOMER ORDER NO.
B	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
01/06/89	01/16/89	DE 9-84	7635171	7 308	R 89-01964

ACCESSORIES W/STUDS

FROM:
DAVE'S GUN SHOP
R D # 3 BOX 726
DRUMS PA 18222

SHIP TO:
DAVE'S GUN SHOP
R D # 3 BOX 726
DRUMS PA 18222

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐			UPS

DEAR CUSTOMER:
WE ARE RIGHT IN THE MIDDLE OF OUR MOST BUSY TIME OF THE YEAR IN SERVICING GUN RETURNS FROM ACROSS THE USA AND CANADA. IF OUR REPAIR TURNAROUND TIME IS A BIT LONGER THAN USUAL, IT IS BECAUSE WE WILL NEVER CUT CORNERS JUST TO RUSH THE GUN BACK TO YOU. WE ALWAYS STRIVE TO GIVE YOU A QUALITY REPAIR IN COMBINATION WITH AS TIMELY A GUN RETURN AS POSSIBLE. SO PLEASE BEAR WITH US AND THANK YOU FOR YOUR SUPPORT.

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

MAIN FAULT

S.L. -.0125"
T.P. - 4½#

PARTS

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RO6P23 REV. 6/88

OFFICE COPY