

RECEIVING AND ESTIMATING REPORT ✓

INITIAL		CUSTOMER ORDER NO.		COMMENTS			
JJM		D19661					
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE		ORDER	
08/31/90	09/11/90	LO 2-77	A6421718	700 30-06 BDL		R 90-236	
ACCESSORIES		W/STUDS					

FROM:

JAY'S SPORTS
N.88 W. 15263 MAIN ST.
MENOMONEE FLS WI 53051

SHIP TO:

JAY'S SPORTS
N.88 W. 15263 MAIN ST.
MENOMONEE FLS WI
53051

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
				9-14-90	UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION:

☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

Occasionally fires when safe is pushed off. Rust in Bore

MAIN FAULT

No fault found - cannot duplicate complaint - Trigger and safety assembly operate properly. Trigger pull 4 1/2 lb, Sem-lift 6008.

PARTS	<i>Offer to return rifle as-is or, if it will better restore confidence in rifle, offer to replace trigger assembly at 1600 - choice, as gesture of good-will.</i>					
	<i>Either option subject to \$10.00 handling plus return postage.</i>					
	<i>Send separate justification for barrel replacement</i>					
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN	
KBA						
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE	

OFFICE COPY

RD6925 REV. 6

PPS 02575