

REPAIR TAG
41794

LARRY'S SPORT CENTER
60 Oregon City, Oregon 97143
OREGON CITY, OREGON 97143
(503) 638-1111

COMMENTS

ORDER
R 94-13066

CUSTOMER EDDIE D. CRAIG COPY NO. E 41794
 ADDRESS P.O. Box 156 145. AHELE
 MODEL OR SERIAL NO. Rem 700 ADL PHONE 845-6879
 TROUBLE REPORTED #369696 - GUN FIRED WHEN
SAFETY WAS PUSHED O.K. - TWO OCCASIONS
 DESCRIPTION OF MATERIAL USED NO CASE - NO SLIDE - NO
SLING - WEAVED BASES ON -
 RECEIVED BY _____
 TOTAL MATERIALS _____
 LABOR _____
 TAX _____
 TOTAL _____
 INSURANCE _____
 UPS _____
 PARCEL POST _____
 TOTAL _____

CERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
	A1	B1				
UP		B2			E1	F1
SY.		B4		D1	E3	F3
		B5		D2	E4	F4
			C1	D3	E5	F5
			C2			

AULT

*Thanks to buyback the customer comment. Rifle rep. in Sept. 1960.
 Remington did send a magazine with rifle return, from which part of
 Henry's comment. Also found in return and trigger assembly. Rifle needs
 a good cleaning.*

COMMENTS

*Capacitor replaced trigger assembly
 and clean action at 1/2 normal
 adjustment cost, as a gesture of good
 will.*

Go ahead!

REPAIRMAN _____ PROOF _____ CLEAN ☒ TEST ☒ TARGET _____ PATTF _____
 GALLERY TESTER _____ DATE _____ DATE _____ DATE _____ DATE _____ DATE _____