

RECEIVING AND ESTIMATING REPORT

CUSTOMER ORDER NO.			COMMENTS		
			POTTER		
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
11/09/87	11/11/87	DI 9-76	A 6357428	700 7MMAG RDL	R 87-22175
ACCESSORIES		SCOPE BASE			
W/STUDS					

FROM:	SHIP TO:
ROSSFORD POLICE DEPT. % MATTHEW BRICHTA - 99 HILLSDALE AVE. ROSSFORD, OH.	
43460	

COUNT NUMBER	FROM DATE	ESTIMATED	VIA
			UPS
PAIR CHARGE	TAX ST	INSURANCE	UPS
	TAX CITY		PARCEL POST
			TOTAL
			\$

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ QUOTE

CUSTOMER'S COMPLAINT
"when the safety was moved to clear the chamber round, the rifle discharged"

MAIN FAULT:
Trigger assembly has been grossly mis-adjusted. Trigger pull 11# 1/2, no return spring force, not enough engagement - seen left O.K. @ 0.013"

ARTS	DEMERIT CODE
------	--------------

	<i>re-adjust trigger properly - return to customer</i>
	<i>charge appropriate amt. for work</i>
	<i>12/2/87</i>
	<i>JAS</i>

FOR COMPUTER REF. ONLY			PROOF
			(CLEAN) (TEST) (TARGET)
			REPAIRMAN

OFFICE COPY

RD6925 REV. 3/8