

air # : K10998 Received : 91/12/05

o See Repair # :

tomor : WM 946

Return Claim Number : 01-0946-968

ress : STATE HWY 34

ress : RT 3

ty, State Zip : PIEDMONT, MO 63957

ke : REMINGTON

Model : 700

l/Ga : 270

Serial # : C6275546

ite to Factory : 92/02/28

Shipping Cost : 6.13

ite Signed :

F C # : D022 7487 914 F Sign :

actory Repair # :

Date Returned from Factory :

ate to Customer :

Insured Value :

ate AOD Signed :

C C # :

C Sign :

ate of Inquiry :

Person Inquiring :

aiting Auth. : Signer :

Charges :

aiting Parts : Part Numbers :

Part Waiting On :

Waiting On Response :

Amount of Charges :

Comments : TRIGGER PROBLEMS.--SEE CUSTOMER LETTER

Explanation of Charges :

Tracer Information

Date/Sent:

Date/Received:

Serial Number Changed : Originally :

New :