

## RECEIVING AND ESTIMATING REPORT

|                           |                         |                          |                          |                   |                                    |
|---------------------------|-------------------------|--------------------------|--------------------------|-------------------|------------------------------------|
| INITIAL<br>FSS            | CUSTOMER ORDER NO.      | CALL TAG ATTN: JACK KAST |                          | ORDER<br>94-13738 |                                    |
| DATE RECEIVED<br>07/20/94 | DATE OPENED<br>04/21/94 | DATE CODE<br>ES 10-69    | SERIAL NUMBER<br>6284774 | NEW SERIAL NUMBER | MODEL AND GRADE<br>700 7MM MAG BDL |
| ACCESSORIES<br>W/STUDS    |                         | L/SIGHTS                 |                          |                   |                                    |

FROM:

SHIP TO:

THOMASIAN, JACK  
14119 BADE DR.  
HARREN

MI 48093

THOMASIAN, JACK  
14119 BADE DR.  
HARREN

MI 48093

CUST NO: 096333 C.L.O.D

|                                                                                                                                                                                                                                     |                              |                                |            |           |               |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|--------------------------------|------------|-----------|---------------|
| ACCOUNT NUMBER                                                                                                                                                                                                                      | ACCOUNT NUMBER N/C<br>059015 | WRITE <input type="checkbox"/> | PROM. DATE | ESTIMATED | VIA<br>UPS    |
| GUN CONDITION                                                                                                                                                                                                                       |                              |                                |            |           | REPAIR CHARGE |
| <input type="checkbox"/> NEW<br><input checked="" type="checkbox"/> LIGHTLY WORN<br><input type="checkbox"/> WORN<br><input type="checkbox"/> VERY WORN<br><input type="checkbox"/> UNREPAIRABLE<br><input type="checkbox"/> MARRED |                              |                                |            |           | EXCISE        |
|                                                                                                                                                                                                                                     |                              |                                |            |           | TAX           |
|                                                                                                                                                                                                                                     |                              |                                |            |           | INSURANCE     |
|                                                                                                                                                                                                                                     |                              |                                |            |           | UPS           |
|                                                                                                                                                                                                                                     |                              |                                |            |           | PARCEL POST   |
|                                                                                                                                                                                                                                     |                              |                                |            |           | TOTAL         |

| CUSTOMER CONCERN | AMMO | FUNCTION | FINISH | ACCURACY | FIT | INSPECT |
|------------------|------|----------|--------|----------|-----|---------|
| CYCLE            |      |          |        |          |     |         |
| RIGGER GROUP     |      | B2       |        |          | E1  | F1      |
| BOLT ASSY.       |      | B3       |        |          | E2  | F2      |
| BARREL ASSY.     |      | B4       |        | D1       | E3  | F3      |
| REC. ASSY.       |      | B5       |        | D2       | E4  | F4      |
| WOOD             |      |          | C1     | D3       | E5  | F5      |
| METAL            |      |          | C2     |          |     |         |

VIN FAULT

Gun mfgn 10/64 Unable to duplicate customer concern as rec'd. Inside of trigger housing had grease like lubricant on side plates and trigger very gummy. Otherwise very well maintained. Replaced trigger Assy at N/C as gesture of good will and to restore customer confidence.

RTS

COMMENTS

Trigger pull measured 5+0.5 1/2  
LBS as rec'd. sear lift was  
.0105

12/21/94  
\*ALSO Grease in trig. Housing/Rec.  
N/C. Look's Like R 109

|                |       |       |      |        |         |
|----------------|-------|-------|------|--------|---------|
| REPAIRMAN      | PROOF | CLEAN | TEST | TARGET | PATTERN |
| GALLERY TESTER | DATE  | DATE  | DATE | DATE   | DATE    |

OFFICE COPY

RD6925 REV. 1/94

PPS 05059