

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 94-16811

INITIAL

CUSTOMER ORDER NO.

ATTN KEN GREEN

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

05/25/94

05/26/94

PH 6-87

B6864898

700 270

RS

ACCESSORIES

FROM:

SHIP TO:

WHITE ELEPHANT
E 12614 SPRAGUE
SPOKANE

WA 99216

WHITE ELEPHANT
E 12614 SPRAGUE
SPOKANEWA
99216

CUST NO: 049613 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

059015

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☒ NEW☒ SLIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Mfg. 6-87 Unable to duplicate concern as recd. Safe is harder than normal to push off. Took trigger assy. apart and still unable to find any fault. Customer may have inadvertently pulled on trigger while repairing safe. Exchange trigger assy. at N/C as gesture of good will.

PARTS

COMMENTS

Trigger pull measured 4 to 4 1/2 lbs as recd. Last lift was .0125

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PPS 05428