

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-24860

INITIAL JJM	CUSTOMER ORDER NO.					
DATE RECEIVED 11/13/92	DATE OPENED 11/19/92	DATE CODE AV 3-79	SERIAL NUMBER A6728733	NEW SERIAL NUMBER	MODEL AND GRADE 700 7MM MAG	BDL
ACCESSORIES W/STUDS		SCOPE BASE				

FROM:

SHIP TO:

CLASSIC GUNS & COLLECTIBLES
1868 MT MEIGS RD
MONTGOMERY

AL 36107

CLASSIC GUNS & COLLECTIBLES
1868 MT MEIGS RD
MONTGOMERYAL
36107

CUST NO: 070422 C.O.D.L.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
GUN CONDITION						REPAIR CHARGE
☐ NEW						EXCISE
☐ LIGHTLY WORN						TAX
☐ WORN						INSURANCE
☐ VERY WORN						UPS
☐ UNREPAIRABLE						PARCEL POST
☐ MARRED						TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	"When either unloading the rifle, i.e. removing a shell from the chamber, or placing a shell in the chamber and closing the bolt, the rifle has spontaneously discharged".			E1	E1	
BOLT ASSY.	B3				E2	
BARREL ASSY.					E3	
REC. ASSY.	B5		D2	E4	F4	
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Could not duplicate complaint. Rifle operates normally. However, disassembly of rifle revealed much rust & rust on under side of barrel, recoil bedrest, receiver and trigger assembly - needs good cleaning.

Trigger pull 4 1/2 Pounds; sear lift .007"

PARTS	COMMENTS				
	Rifle needs good cleaning on bottom of bolted action				
	Offer following options:				
	1) To clean rifle & return with present T.A.				
	2) To clean rifle & replace trigger assembly at a normal cost, as a gesture of good will if that will gether restore confidence in the rifle.				
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

PS01527