

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 95-19301

CUSTOMER ORDER NO.

W/REDFIELD 1 3/4 X 5X SCOPE

RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
7/28/95	07/31/95	EU 10-71	6484954		700 300 WIN MAG/BDL
ISSORIES	W/STUDS	SCOPE MNTS	SCOPE BASE	L/FRONT SIGHT	

W:

SHIP TO:

DUNN, MIKE
RT 3 BOX 256
SPANTA

GA 31087

DUNN, MIKE
RT 3 BOX 256
SPANTA

GA
31087

CUST NO: 123335 C.O.D L

QUANTITY	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
CONDITION					UPS
NEW					REPAIR CHARGE
SLIGHTLY WORN					EXCISE
WORN					TAX
VERY WORN					INSURANCE
UNREPAIRABLE					UPS
MARRED					PARCEL POST
					TOTAL 33.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
BLE	A1	B1				
GREY GROUP		B2			E1	F1
ST ASSY.		B3			E2	F2
REL ASSY.		B4		D1	E3	F3
ASSY.		B5		D2	E4	F4
OD			C1	D3	E5	F5
FAL			C2			

FAULT: *Mfg. 10/71 All three trigger adjusting screws have been altered outside of factory - not recommended! Trigger 'pounds pull' spring misaligns. Replace trig. Assy. at a spec. price strictly as a gesture of good will.*

TS	Trigger Assy		COMMENTS			
REPAIRMAN		PROOF	CLEAN	TEST	TARGET	PATTERN
			☒	☒		
GALLERY TESTER		DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6628 REV. 1/84