

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 194-24611

INITIAL CUSTOMER ORDER NO.

W/LEUPOLD 1.75X6 SCOPE & CAPS
METAL PAINTED CAMO

Za Cabinet

RECEIVED DATE OPENED DATE CODE SERIAL NUMBER NEW SERIAL NUMBER MODEL AND GRADE
25/94 08/26/94 BB 1-81 B6237651 700 30-06 LH
ACCESSORIES L/MAG BOX L/WOOD L/FOLLOWER L/MAG SPRING SCOPE MNTS
W/SCOPE BASE

FROM:

SHIP TO:

FALETTI, DAVE
P.O. BOX 759
406 S. 9TH
SPIRIT LAKE

ID 83869

FALETTI, DAVE
P.O. BOX 759
406 S. 9TH
SPIRIT LAKE

ID
83869

CUST NO: 096293 C.O.D.L.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

Product Service

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3				
BARREL ASSY.		B4				
REC. ASSY.		B5				
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Left May 1981
We could not duplicate the report concern. Examination revealed that the trigger has been painted the barrel and receiver. Some paint has gotten on trigger and the safety assembly. The action and trigger housing is bound with a unit substance. But also found on action. The rifle has been properly maintained.

PARTS

COMMENTS

Steve Stock & Hardware

3290.5

Replace the complete trigger assembly and clean the action at 1/2 normal replacement cost, as a gesture of good will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
CC		✓	✓	✓	✓
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

R05925 REV. 1/94