

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs

800-243-9700

Fax

336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number	Description/Serial Number	Date Received -
RE00047668	6291321	6/11/2002
Account # - R-	Model 700 Center Fire Caliber: 3006 BDL	Estimate Date - 6/5/2002
		Current Date - 6/13/2002
Customer	Return To	
JAMES LOWE	JAMES LOWE	
5295 RICHARD DR	5295 RICHARD DR	
BEAUMONT, TX 77708 US	BEAUMONT, TX 77708 US	
Phone (H) (409)-892-4567	Fax	
Phone (W)	Email	

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE	M123	FORWARD TO PRODUCT SERVICE FO
	FOR INSPECTION	M238	CLEAN & INSPECT
M238	CLEAN & INSPECT	M239	REPLACE TRIGGER ASSEMBLY

Technician's Comments	
ProblemNotes	coulds not duplicate concern..altered adjustment screws,sticky residue inta.quote \$20 for cleaning action and new ta under bolt lock mod program per product service

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part	Total:	1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	20	N
4000119	GR-TEST	10	Y
4000294	GR-CHECK TPA	1	Y
Service	Total:	31	


10 LBS 1 OF 1

REMINGTON ARMS CO INC
800 243-9700
14 HOEFER AVE
ILION NY 13357

SHIP

TO:

JAMES LOWE
5295 RICHARD DR
BEAUMONT TX 77708-1921




TX 777 0-01



UPS GROUND

TRACKING #: 1Z 114 813 03 1189 5902



BILLING: PREPAID

INV#: RE00047668

ASC 3.70 J69K/J64K 14.0 01/2002