

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700
Madison, NC 27025-0700

Parts/Repairs 800-243-9700
Fax 336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00047971 Account # - R-	Description/Serial Number 6515427 Model 700 Center Fire Caliber: 3006 ADL	Date Received - 6/14/2002 Estimate Date - Current Date - 6/19/2002
Customer ROBERT VANDE WALLE 2550 PARKWOOD DR GREEN BAY, WI 54304 US	Return To ROBERT VANDE WALLE 2550 PARKWOOD DR GREEN BAY, WI 54304 US	
Phone (H) (920)-496-6715 XW Phone (W) (920)-498-9363 XH	Fax Email rvandewalle@new.rr.com	

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M239	REPLACE TRIGGER ASSEMBLY
M238	CLEAN & INSPECT		

Technician's Comments	
ProblemNotes	Could not duplicate. Trigger assm. settings altered. Install new trigger assm. clean action under bolt lock safety modification program.

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part	Total:	1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	20	N
4000118	GR-CLEAN	1	Y
4000119	GR-TEST	1	Y
4000294	GR-CHECK TPA	1	Y
Service	Total:	23	


10 LBS 1 OF 1

REMINGTON ARMS CO INC
800 243-9700
14 HOFER AVE
MILTON NY 13357

SHIP

TO:

ROBERT VANDE WALLE
2550 PARKWOOD DR
GREEN BAY WI 54304-1942




WI 543 9-50



IPS GROUND

TRACKING #: 1Z 114 813 03 1190 0084



BILLING: PREPAID

NV#: RE00047971

ASC 3.70 J69X/J64X 14.0 01/2002

PS06333