Remington Arms Co., Inc. **Product Service** Legal Case #:2755

Case Information

Date Opened Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete RE#

10/3/2008 152194 10/2/2008 10/3/2008

Customer Information

Business First Name Last Name Street City Zip Age Contact Type 110 N Main Ave FL Minneola 34715 H 352-516-7863 Incident Nicholas LaRoche

Incident Information

Codes Repair Est. Medical Treatment Medical Status Claims

PΙ

Improper Maintenance PD Cause:4015

Unknown

S fired on safe release

Concern:1007 Fired on Safe Release

Customer says "When a round is loaded into the chamber, the firing pin is already engaged. When a round is loaded with the safe on, the firing pin is in firing position; but, when the safety is disengaged the gun fires without touching the trigger."

Firearm Information

Model/Ga. SKU Serial Bbl. **DOM** Mfg. Type

11/24/2003 7:40:04 25939 F6281767 RX CF/BA 700/270 WIN Remington AM

Original Date Where Purchased Accessories Purchased Owner

WAL-MART DC 6003R-TWO PIECE SCOPE U

REGULAR **BASE**

CONCERN:FSR

Ammunition Information

Type Cal./Ga. SKU **UPC** DOM Mfg. Code Mfg.

Remington CL /150

Concern Other Factory Reload Y 0: N

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Cash Release of Claims Settlement Release Date Date Reimbursement Date Settlement APV APV

Repair as needed at special price

> Repair/Replacement Repair/Replacement

Cost Date

Trigger and trigger pin rusted and not properly returning under sear due to improper maintenance. Returned to AS to clean action, check over completely, and install a new TA at 1/2 normal charges as gesture of goodwill fls.

Examination[Remington/CF/BA]

| - 1 | | | | |
|-----|--------|---------------|-------|-------------|
| - 1 | TD .4 | C 1 D4 | C. 1. | l |
| - 1 | l Part | Sub-Part | Code | Comment I |
| - 1 | | | 0000 | |
| - 1 | | · | | |

Cash

Reim.

| | Examiner | | B.TRAVIS |
|---------------------------------------|--------------------------------|----------------------------------|---|
| | Exam Date | | 10/3/2008 |
| Examination | Product Type | | RF |
| | Action Type | | A |
| | Assigned To | | F.SUPRY |
| Cause | 4015 | Improper Maintenance | |
| | Description | | 22" 270 WIN |
| · | Date Code | | RX |
| | Bore Plugged | False | |
| Barrel | Bulged | False | |
| | | False | |
| | Fired while Obstructed | | |
| | | Slightly Worn; Functioning | 1 |
| | Firing Pin | Slightly Worn; Functioning | |
| | Shroud | Slightly Worn; Functioning | |
| Bolt | Face | Slightly Worn; Functioning | |
| Bon | Handle | Slightly Worn; Functioning | |
| | Stop | Slightly Worn; Functioning | |
| | Condition | Slightly Worn; Functioning | |
| Estende | Cut Condition | Slightly Worn; Functioning | |
| Extractor | Ext/Eject Test | False | |
| | Block Condition | Select | |
| , , , , , , , , , , , , , , , , , , , | | | |
| Locking | Lug Condition Notch Condition | Slightly Worn; FunctioningSelect | |
| | | | |
| 011 | Exterior Condition | Slightly Worn; Functioning | • |
| Overall | Stock Condition | Slightly Worn; Functioning | |
| | Fore End Condition | Select | |
| Receiver | Condition | Slightly Worn; Functioning | |
| | Bulged | False | [m. 1277 1 P. 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 |
| | Description | L | STANDARD M/700 SAFETY |
| Safety | | Like new; Functioning | |
| | | ISS | [|
| ear | Lift | Select | .017 |
| | Notch | Like new; Functioning | |
| | Tests | Test Fired | False |
| Feeding Test | | False | |
| rigger | | | TRIG AND PIN RUSTED BINDING |
| | Pull | Select | 10+# |
| 3 0 | Altered | False | |
| | | M/700 Non-Bolt Lock | |
| Non-Remington Components | Description | | TWO PIECE SCOPE BASE |

PS 09820

| pair Inquiry | | | | | |
|--|--|---------------------------------|--|--|--|
| air Number RE00152194 | Serial F6281767 Model 70 270 WIN. Produced, 11/24 | לייייי | Bruce Travis ApprovalHold:10/3/2008 | | |
| y Repail Tress Information | |) Jack | Аррочаная 10/3/2008 | MA UCUCC | |
| Customer | | Réturn To: NICK LAROCHE | — C Receiv | ved From | |
| Name: NICK LAROCHE (ess.): 110 N. MAIN AVE. | The American State Court | J110 N. MAIN AVE. | on a decimanda (1981) e assurante a patricio del Constanto de Santo | | |
| ressi2: | PO Box | CLERMONT | PO Box | | |
| City CLERMONT State FL Zip Code: 34715 | Country JUS | State FL Zip Code 34715 | Country US | | |
| | Talana da sa | FFL F F F F F | | | |
| Contact / Condition | Problems | Estimate History / SI | atus Shipping | g / Billing | |
| le vis | The transfer of the | | Current: | Sialus | |
| ate Code // Co | UserID Desc1 sanguineg/ Repair Add | Medium 1 | The second second | AHad 53050AM | |
| 0/2/2008 12 53 Expedite 0/2/2008 2 31 C Update | pencerl From: Cher Valentds Repair info | ±k In Interra rmation change | T. 2 | A | |
| 0/2/2008/2/31(0) Expedite | Valentds From: Chec | illiaduri Grenge | Received Apploy | CONTRACTOR OF THE PARTY OF THE | |
| 0/3/2008 5:28 | | | finspection IL | ocation N | |
| 0/3/2008/7/27/5 Expedite | Travisbw Estimate U pencerl From: Repo | J Heturn | As Received Current L | ocation N | |
| | | | Criappioveu Transfer | the state of the s | |
| | | <u>.≱</u> Filinleina | гнерай | | |
| Repair Search | | | D4 L | | |
| Repair <u>S</u> earch | | | <u>R</u> efresh | Close | |
| | | | And the state of t | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | est recommendations | | | |
| | | | | | |

Returned to AS for repair Charge 1/2 normal as gesture of goodwill.

> DECEIVE L OCT 0 7 2008 BY:

Factory Repair Instructions

| (NOTE: Ficase print and complete this for | in, and then include it with your firearm.) | | | | |
|--|---|--|--|--|--|
| Model Number: 700 | Serial Number: F6281767 | | | | |
| Are you the original owner?: NO | | | | | |
| Name: Nicholas La Roche | Date of Purchase: | | | | |
| Address (no PO Boxes): 110 N. Main Ave. | | | | | |
| · · · · · · · · · · · · · · · · · · · | | | | | |
| city: Minnesha | State: FL Zip: 34715 | | | | |
| Phone (Daytime): 352-516-7863 | Fax: | | | | |
| E-mail Address: I would like to receive future e-mail updates from Remington. | | | | | |
| Please describe your problem: When a ro | und is loaded into the | | | | |
| chamber, the fireing pin 15 a | Tready engaged, When a | | | | |
| round is loaded while the | safety is an the fireing | | | | |
| pin is in firing position, but when the safety is | | | | | |
| disensured, the ann fires without touching the | | | | | |
| triagrer | | | | | |
| 93 ' | | | | | |
| The second secon | | | | | |
| Ammunition Information: | | | | | |
| Manufacturer: Remington | Type: Core-Lok+ | | | | |
| Other (i.e. bullet weight/type, shot size, powder): | | | | | |
| | | | | | |
| Handload Information: | | | | | |
| Powder Used: | Powder Weight: | | | | |
| Case/Hull Used: | Primer Used: | | | | |
| Bullet Type/Shot Size: | Reloader Used: | | | | |
| | | | | | |
| Firearms Care (Cleaning and Lubrication): | | | | | |
| Brand of cleaning solution used: Hopnes | | | | | |
| How often do you clean the bore? (Months or Number of rounds) | | | | | |
| How often do you clean the action? (Months or Number of rounds) 40 rounds | | | | | |
| How often do you clean the trigger assembly? (Months or Number of rounds) | | | | | |
| | | | | | |
| Brand of lubricant used: 1700089 | | | | | |
| | The Distriction | | | | |

TRIG. + TRIG. PIN MITTED & BINDING.

Replace TRA, checkover, chem AT

1/2 Normal cost.

Ocuste

How often do you lubricate the bore? (Months or Number of rounds)

How often do you lubricate the action? (Months or Number of rounds)

How often do you lubricate the trigger assembly? (Months or Number of rounds)

you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?

Comments:

When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?

What were the services performed?

Ship your INSURED firearm by either UPS or Parcel Post to:

REMINGTON ARMS CO., INC

ATTN: Arms Service Divison - 14 Hoefler Ave -Ilion, NY 13357

■WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM, THIS IS A VIOLATION OF FEDERAL LAW: IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

- :: Record the serial number of your firearm before sending it.
- :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)
- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.
- :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please your gun)

nate detailing the nature of the repair, applicable taxes estimate. Repairs can be paid by check, money order, r VISA). If you wish, you can expedite repairs over led to your credit card.