î

`	Produ	n Arms Co., Inc uct Service Case #:8096					
Case Information							
RE# Date Opened Date Opened 287196 10/26/2012 10/29/201		Date Closed 10/29/2012	Incident Da	te Pr	e Lit	Lit (Obsolete X
Customer Information							
Type Business First Name Last Nat	ne	Street	City	State	Zip	Age	Contact
Incident Ronald Dubuqu	ie 33 /	Adam School Re	d Grand Isle	vt	05458		
Incident Information							
Claims	Codes		Repair Est. M	edical Tr	eatmen	t	ledical Status
PI							
PD Cause:4013 Broken or Missing							
Fired when safety was	Parts Concern: 1007 Fired on Safe Release			Unknown			
C							
11/8/12 Per note on SR, consumer claims when f	lipped from	safe to fire, the	rifle fires.cm				
Firearm Information							
Mfg. Type		Model/G	Ga. Sh	U	Serial	Bb	I. DOM
Remington ML/BA		700/54 C					6/4/1996
Date Where Purchased	I	Accessor	ies Orig	jinal			
DICKS CLOTHING & SP GOODS	ORTING	AFT MKT KIT	²⁰⁹ t	J			
CONCERN: FSR							
Ammunition Information - None Defined							
Other Products Information - None Defined							
Settlement							
	Remingto	on/700/ML/BA					_
Settlement Release of Claims	Relea	ise Date R	leimbursement	Cash Settlem	ent]	keim. Date APV	Cash Date APV
Per Ilion, check over and repair TPA at no charge.					_		
Repair/Replacement Cost	~	eplacement Date					
34.21	11/8	3 /2012					
11/8/12 Per Ilion, connector broken. Check over	and repair T	PA at no charge	e.cm				

Examination[Remington/ML/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		10/29/2012
Examination	Product Type		RF
	Action Type		A
1	[]		

	Assigned To		T.NAGLE
Cause	4013	Broken or Missing Parts	CONNECTOR BROKEN
· ·	Description		24" 54 CAL SS
	Date Code		PQ
	Bore Plugged	False	
Barrel	Bulged	False]
	Fired	False]
	Fired while Obstructed]	
	Muzzle/Crown Condition	Slightly Worn; Functioning]
	Firing Pin	Select	AFT MKT
	Shroud	Select]
Bolt	Face	Select]
	Handle	Slightly Worn; Functioning]
	Stop	Select]
	Exterior Condition	Slightly Worn; Not Functioning]
Overall	Stock Condition	Slightly Worn; Functioning]
	Fore End Condition	Select]
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False]
	Description		STANDARD SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS]
	Lift	Select	N/A
Sear	Notch	Slightly Worn; Functioning]
· · · · · · · · · · · · · · · · · · ·		Test Fired	False
Feeding Test	= Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	CONNECTOR BROKEN
	Pull	Select	N/A
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock]
Non-Remington Components	Description		AFT MKT 209 KIT

Service Request

.

Remington Service

PO Box 700 Madison, NC 27025-0700



Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number SR00031989	Serial Number / Description	8096	1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1	16/2012 16/2012
51(00051)05	Model 700ML RIFLE Caliber: 54		Date Timited. 10	10/2012
Customer:		Destination:		
RONALD DUBUQUE 33 ADAM SCHOOL R	٦	Arms Services		
GRAND ISLE, VT 05		14 Hoefler Ave Ilion, NY 133		
	60 864	1101, 141 155	ji US	
Email:		Email:	,	
		to determine if it is covered under our warranty	/ policy. If it is your firearm will	be repaired and
returned. If not, you will be co	ontacted with an estimate before work is perf	formed.		
				ļ
				а.
		· .		
				ALL SILLS
Reason For Return			1 10 . •	
M993 - SAFETY				
Service Request Section :				
e i de la contra de la contra entre entre de la contra de la constante de	HEN FLIPPED FROM SAFE TO FIRE	E, THE RIFLE FIRES.	ഷം പെടു ത്തും പ െട്ടില് പോലും വുടും പോലും പുറം. പ	ana ang atan na malang sagangan (ga pas)
				1
		· · · ·		.
				5. C
Parts And Service Details Material Type	Description	Qty Warranty	Price Di	sc Amount
Material Type	Description	Qty Warranty Needed		sc Amount
ML009	351			
		MECEIVE		
Model: 70	ØML_			
	LER TERME ENITE INCOMENTAL INTERNAL INTERNAL	LL (CT 3 1 20.2 型		
		BY:	(
		Collear for	is proten.	
DEO	0207106	CONCE ION	- (5 (b) • • •	
		clash and	a Lilen. TRA	
		Chech own	re l'ope i	
·		at ille		
		N/C	atilip. TRA	
		<u> </u>	Sal	
		£2	3014.2	
		、		
				I
			•	
				ļ
THIS IS NOT AN INVOICE.	This is a pre-estimate to repair, recondition, o	or replace the item(s)	Sub Total:	.00
being sent based on the conver			Est Sales Tax:	.00
		•		1
		· · · · · · · · · · · · · · · · · · ·	Grand Total:	\$.00

BEECROFT'S SINCE 1949 11106 STATE ROUTE 40 SCHAGTICOKE, NY 12154 3 MILES NORTH OF SCHAGTICOKE SPECIALIST IN FIREARMS, RELOADING EQUIPMENT & SUPPLIES PHONE (518) 753-4402 FAX (518) 753-4403

Customer' Order No.		Date	11-26	03			
Name	This Strugnes						
Address 1593 Ctr Rts 49							
ARGY18 NY. 12809							
SOLDBY	CASH C.O.D. CHARGE ON ACCT. MIDSE. RET	D. PAILO	ur				
Quantity	DESCRIPTION	PRICE	ANC	UNT			
-1	54 CAL Romination		249,	95			
	# ML 00 9351						
1	PIRODOY 54/60 Pollata		22	95			
1	Black Bow DSR Solvent		5	99			
1	54 cm (Hornad subst		6.	49			
1	BORS ButtsR		7.	49			
1	Stanight liss LAPFOR		8,	95			
ŀ	NO 11 Mazon		3	29			
		•					
	Ω		305	11			
	1/2 / 1 9						
	MANY 12						
		TAX	22	12			
		TOTAL	327	23)			
ALL claims and returned goods MUST be accompanied by this bill.							
UUUJIZZ Rec'd by							

2

Thank You

Reorder from PRXAR (800) 543-8650

1

Form #NC-3501