Remington Arms Co., Inc. Product Service Legal Case #:9282

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

326008 10/31/2013 11/1/2013 11/6/2013

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Incident Ashley Mishoe 114 Pine Tower Circle Swansea SC 29160 H 803-730-7557

Incident Information

Claims Codes Repair Medical Medical Est. Treatment Status

PΙ

1st time shot hole in hse Cause:4013 Broken or Missing

PD wall, 2nd time shot hole in stand Parts
Unknown

stand Concern:1020 Fired on Bolt Opening

C

10/9/13: Customer called in. He stated he opened the bolt & the gun discharged on 2 different occasions - No injury. He said the 1st time caused a hole in his house wall and the 2nd time shot a hole in tree stand. Customer said it happened last year but he could not remember any dates. He said he put the gun in his safe & bought a different brand of rifle to use. df

Firearm Information

Mfg. Model/Ga. SKU Serial Bbl. DOM Type 770/300 WIN 11/16/2007 1:26:56 71411967 RB Remington CF/BA 85636 MA AM Date Original Where Purchased Accessories Purchased Owner

Purchased Walt-Mart Accessories Owner

SUPERCENTER 0881

CONCERN:FBC, SHOT HOLE THRUOGH WALL & CAR TAIL LIGHT

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/770/CF/BA

Repair @ n/c - goodwill gesture

Repair/Replacement Repair/Replacement Cost Date

\$40

10/9/13: Mailed ARS, letter & SR paperwork. Box order# 1549751. df 11/5/13: I spoke w/customer & went over exam. df 11/6/13: I emailed Ilion to repair at n/c - goodwill gesture. df

http://cps03sp01.remington.com:99/Remington PSA/PrintDisplay.aspx?ID=9282&Type=... 11/6/2013

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		11/1/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4013	Broken or Missing Parts	TRIGGER HOUSING IS BROKEN
	Description		24" 300 WIN MAG
	Date Code		RB .
	Bore Plugged	False	
Barrel	Bulged	False	
Darrei	Fired	False	
	Fired while Obstructed		•
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Condition	Select	
Magazine	Box Condition	Missing	
	Exterior Condition	Slightly Worn; Functioning	ACTION VERY DIRTY SOME LIGHT RUSTING
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
Sear	Lift	Select	N/A
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding	Tests	False	

 $http://cps03sp01.remington.com: 99/Remington_PSA/PrintDisplay.aspx?ID=9282\&Type=... \quad 11/6/2013$

Test			
Trigger	Condition	Slightly Worn; Not Functioning	HOUSING BROKEN
	Puli	Select	4.5#
	Altered	False	
	Sub-Assembly	Other Remington]

emington. Copy

October 9, 2013

Ashley Mishoe 114 Pine Tower Circle Swansea, SC 29160 Phone: 803-730-7557

Ref # 9282, Model 770, Serial # 71411967

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory. A rifle box will arrive separately.

Please include a copy of this letter and service request to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm.

> Sincerely, Dell Fulcher Consumer Affairs Administrator Remington Arms Co, LLC Phone: 1-800-243-9700 ext 8686

Fax: 336-548-7872

Model:

Service Request

Remington Service

Madison, NC 27025-0700



Grand Total:

\$.00

ATTN: Product Service

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number | Serial Number | Description 10/09/2013 Date of Request: SR00063992 71411967 Date Printed: 10/09/2013 Model 770 RIFLE Caliber: 300 Customer: ASHLEY MISHOE Destination: Arms Services 14 Hoefler Ave 114 PINE TOWER CIRCLE SWANSEA, SC 29160 US Ilion, NY 13357 US Email: Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed. Reason For Return M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION Service Request Section Product Service # 9282. dmf Parts And Service Details Material Type Description Qty Needed Warranty Price Disc Amount THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) .00 Sub Total: being sent based on the conversation with our representative. Est Sales Tax: .00

September 2 Septem				
Model Number:	Serial Number:			
770	71411967	71411967		
Name:	Date of Purchase	Date of Purchase:		
Ashley Mishoe	4 or 5 years ago			
Address (no PO Boxes):				
114 Pine Towers C	irde	and the same of th		
City: Swansea	State: 30	Zip: 29/60		
Phone (Daytime): 130 - 755 7	Fax:			
E-mail Address:	The second secon			
Please describe your problem	n:	***		
When you load - it goes off - fires When you unload - it goes off - fires Shot a hole through I ving room wall and car tail light. Drangerous gun - needs to be replaced.				
500 characters left		<u>.</u>		
NOTE: Prior to shipping your fir provided and estimated repair t	carm, contact the Rep ime	air Center for services		

WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

- :: Record the serial number of your firearm before sending it.
- :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a

firearm box. (Note: Original boxes may not be returned.)

- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss

during shipment, so you may elect to purchase insurance from your earrier,

Use our

ARS LABEL REQUEST FORM

DATE:	10/09/2013	Service Request #	SR00063992
QUANTITY:	ī	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	fulcherdm	email address:	I WILL MAIL LABEL
Business:	· ·• ·	Remineton Service	

LABEL INFORMATION

MAIL LABEL TO: ASHLEY MISHOE 114 PINE TOWER CIRCLE SWANSEA, SC 29160 US

SR00063992

Remington Service PO Box 700 Madison, NC 27025-0700 www.remington.com

Email:

RETURN ITEM TO: ILN

Arms Services

4XX596 OCT 9, 2013 ALL CURR USD SVC GNDCOM ACT WT 10.0 LBS TRACKING# 1Z4XX5969085028352

1 OF 1

REF 1:SR00063992 REF 2:

HANDLING CHARGE 0.00
SINGLE — PIECE PUB RATE CHRGS:
DV 0.00 CD 0
DC 0.00 DGD 0
AH 0.00 PR 0
TOT PUB CHG 11.01 P SVC T/P USD RS 0.50 SD 0.00 SP 0.00 COD 0.00 DGD 0.00 PR 0.00 PUB+ HANDLING 11.01

ATTN: Product Service









