

Remington Arms Co., Inc.
Product Service
Legal Case #:8846

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
308787	4/23/2013	4/24/2013	4/24/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Leslie	Bennington	2245 Morning Dove Dr	Laurel	MT	59044		E lobennington@gmail.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern			
S	Fired when removed from safe Concern:1007 Fired on Safe Release		Unknown	
C				

5/1/13 Per note on SR, fired when moved from safe.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM REM MA	n/a	6869527	PZ	6/1/1975
Date Purchased	Where Purchased	Accessories	Original Owner			
	G SEARS SUPPLY EL RENO OKLA	TWO PIECE BASE	U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	29.04	5/1/2013				

5/1/13 Per Ilion, could not duplicate concern. Set screws altered. Replace TPA, clean, test at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/24/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24"7MM REM MAG
	Date Code		PZ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Scar	Lift	---Select---	.006
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	3.5#
	Altered	True	SEALANT MISSING
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

Service Request

Remington Service

PO Box 700

Madison, NC 27025-0700



Parts and Repairs: P:800-243-9700 F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

24"
P26/7
3.5#
1006

Service Request Number SR00048386	Serial Number / Description 6869527 700	Date of Request: 03/19/2013 Date Printed: 03/21/2013
Customer: LESLIE BENNINGTON 2245 MORNING DOVE DR LAUREL, MT 59044 US	Destination: Arms Services 14 Hoeffer Ave Ilen, NY 13357 US	
Email: lobennington@gmail.com	Email:	
Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.		
Reason For Return: M240 - BOLT LOCK SAFETY MODIFICATION		
Service Request Section: fired when removed from safe - SMP program		
Parts And Service Details		
Material	Type	Description
		Qty Needed
		Warranty
		Price Dhc Amount

Serial Number: 6869527

Model: 700

RE00308787

RECEIVED

APR 26 2013

BY:

could not dup. concern
set screws alt. Rep. TPA
clean + test und. BLP
Cor 20 +
Q

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

Sub Total:	.00
Est Sales Tax:	.00
Grand Total:	\$.00







