

Customer Service Data Entry			
File Number: 5062		Arms Service number: 9702413	
Last Name: VAN LEUNENS		First Name:	
Street: 621 WILMER AVE		City: CINCINNATI	
State: OH Zip: 45226		Home Ph:	
Work Ph: 513 533 2700		Product Type: F A T O	
Type Concern: S PI PD P S C		Concern Code: 1007	
Concern: FIRED ON SAFE RELEASE			
Cause Code: 4015		Cause: IMPROPER MAINTENANCE	
Assigned To: KAST		Classification: UNJ UNJ UNC UND J	
Settlement Detail: REPAIR SPCL PRICE		Settlement Amount: \$0.00	
Date Opened Rem: 1/27/97		Date Opened by P/S: 1/30/97	
Date of Incident:		Caliber: 50CAL	
Date Closed: 1/30/97		Bullet Weight:	
Date to Analysis:		Date from Analysis:	
Manufacturer: REM		Model: 700ML	
Serial: ML011141		Date Mfgd: 6/1/96	
Date Code: PQ		RAMAC: 700ML	
Litigation: ☐		PreLitigation: ☐	
Obsolete: ☐		Custody:	
Comments:			
Time of Modification: 1:00:02 PM		Date of Modification: 1/30/97	

Additional info.

FLTR

CAPS NUM

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 97-02413

INITIAL CUSTOMER ORDER NO.

JJM

W/ACCESSORIES

Product -
Service

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

01/20/97

01/27/97

PQ 6-96

ML011141

700 50CAL

ML

ACCESSORIES

FROM:

SHIP TO:

VAN LEUNENS
DBA ALL ABOUT SPTS
621 WILMER AVE
CINCINNATI

OH 45226

VAN LEUNENS
DBA ALL ABOUT SPTS
621 WILMER AVE
CINCINNATI

OH

45226

CUST NO: 008341 WILM L

ACCOUNT NUMBER

ACCOUNT NUMBER MC

WRITE

PROM. DATE

ESTIMATED

VIA

1/28/97 UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

38.00

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B3

BOLT ASSY.

B4

BARREL ASSY.

B5

REC. ASSY.

WOOD

METAL

MAIN FAULT

Gun fires when safe is taken off
Some - Trigger - Trigger pin & Trigger housing all rusted - Trig
does not return after being pulled. Also; Firing pin -
firing pin spring - inside of breech bolt assy were rusted
as seen.
Exchange trig assy at a spec price strictly
as a gesture of good will.

PARTS

COMMENTS

trig assy.

See owners manual for
proper care and maintenance.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 11/96

ALL ABOUT SPORTS®

A Division of
VAN LEUNEN'S INC.
621 Wilmer Ave.
Cincinnati, Ohio 45226
(513) 533-2700
Fax (513) 321-5884

DATE: 1/15/97

SUBJECT: muzzle loader

UPC NUMBER

□-□□□□□-□□□□□□-□

PLEASE REPLY:

- ☐ URGENT
☐ AS SOON AS POSSIBLE
☐ NO REPLY NECESSARY

Remington Arms Co. Inc.

14 Hoefler Ave

Ilton, Ny 13357

Arms Service Division

del: Remington 700 27572 .50 cal muzzle loader S/N MLO11141

ore Gun

problem: When safety is taken off, the gun fires automatically.

REPLY TO:

Thank-you
GERRIE Botton

(513) 533-2778

SIGNED:

DATE:

01007

SENDER—RETAIN THIS COPY