

M/700 - 264 CAL. EROSION TEST

ACCURACY TEST #7

Repeat of Test #6 - After cleaning and inspection by J. Brooks

Gun # 232246 - A deep scratch was noticed in barrel near muzzle.

Gun #		Group	Hors.	Vert.	
232246	1	2.70	2.35	1.90	
	2	5.30	4.90	3.00	4 shots
	3	6.85	6.80	1.05	4 shots
	4	2.00	0.60	1.90	2 shots
	Ave.	4.21	3.66	1.96	
268627	1	2.10	1.55	1.70	
	2	1.90	1.90	0.85	
	3	2.60	1.45	2.25	
	4	4.50	3.55	3.25	
	Ave.	2.77	2.11	2.01	
268797	1	2.75	1.10	2.75	
	2	1.30	1.45	1.00	
	3	5.00	5.00	1.50	
	4	3.10	3.10	0.95	
	Ave.	3.04	2.66	1.55	
6428918	1	1.90	1.60	1.85	
	2	1.70	1.40	1.40	
	3	2.40	1.45	2.35	
	4	5.10	3.55	4.50	
	Ave.	2.77	2.00	2.54	

WRG:B
12/4/74