

P.I. YES GUN EXAMINATION REPORT NUMBER: 496 MODEL: 700 BDL
 GENERAL CONDITION: FAIR R #: 20402
 OUTSIDE WORK: SCOPE MOUNTS ADDED DATE: 8-12-81
SIGHTS REMOVED FROM: BENTON COUNTY COO.
PA BOX 278 HWY. 3 N.
ASHLAND MISS.
 FIRED AMMO TYPE: NOT KNOWN GUN #: 6499295
 & CONDITION: _____ CODE: BW-1-72
 PROOF: M INSP.: 73 TEST: 97 GA./CAL.: 22-250
 HEADING: OK CHECKED BY: M-HARDY
 BREACH OPENING: OK APPROVED: [Signature] 8/15/81
 RECOIL SHOULDERS: OK APPROVED: [Signature] 8/25/81
 CHAMBER: OK APPROVED: [Signature] 8/25/81
 TEST: _____ APPROVED: [Signature] 8/25/81
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: [Signature] 8/25/81
BRIGHT METAL ON BBL. SLIGHT MARKS ON STOCK
SEAL BROKEN ON FRONTPIG SCREW

COMPLAINT: HAS GONE OFF WHEN SAFETY WAS PUSHED
TO THE FIRE POSITION

INCIDENT: _____

COMMENTS: Trigger pull 2# - adjusted outside of plunger and
resealed with red material.

Unable to duplicate customer complaint.

Repair as customer requested - replace fire control.