

RECEIVING AND ESTIMATING REPORT

INITIAL "B"		CUSTOMER ORDER NO. 1338		COMMENTS ATT DICK ST JOHN/L REAR SIGHT			
DATE RECEIVED 01/09/89	DATE OPENED 01/18/89	DATE CODE CA 4-80	SERIAL NUMBER B6203109	MODEL AND GRADE 700 300 BDL/MAG		ORDER R 89-022	
ACCESSORIES W/STUDS		SCOPE BASE					

FROM:

WILLIAMSON-PATE GUNSMITH SERVI
DBA/GUNCRAFT, INC (PRO
117 W PIPELINE ROAD
HURST, TEXAS

000076053

SHIP TO:

WILLIAMSON-PATE GUNSMITH SER
DBA/GUNCRAFT, INC (PRO
117 W PIPELINE ROAD
HURST, TEXAS

000076053

ACCOUNT NUMBER	ACCOUNT NUMBER N/C 059001	DATE 1/1/89	ESTIMATE 15096
----------------	------------------------------	----------------	-------------------

DEAR CUSTOMER:

WE ARE RIGHT IN THE MIDDLE OF OUR MOST BUSY TIME OF THE YEAR IN SERVICING GUN RETURNS FROM ACROSS THE USA AND CANADA. IF OUR REPAIR TURNAROUND TIME IS A BIT LONGER THAN USUAL, IT IS BECAUSE WE WILL NEVER CUT CORNERS JUST TO RUSH THE GUN BACK TO YOU. WE ALWAYS STRIVE TO GIVE YOU A QUALITY REPAIR IN COMBINATION WITH AS TIMELY A GUN RETURN AS POSSIBLE. SO PLEASE BEAR WITH US AND THANK YOU FOR YOUR SUPPORT.

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐ NEW☒ SLIGHTLY WORN☐ VERY WORN☐ MISUSED☐ MARRED

CUSTOMER'S REQUEST

Trigger Problem

MAIN FAULT

Trigger Assem. out of adjustment

PARTS

#33385

Fit Stock Assembly

RE-adjust Trigger Assem. to function
SPEC. 2pc.

Refile metal parts

Check and return

Work done

REPAIRMAN KRP	PROOF	CLEAN ✓	TEST ✓	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE