

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product Service

ORDER

R 94-04359

INITIAL CUSTOMER ORDER NO.

JJM

BOTTOM HALF OF MOUNTS ONLY

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

02/02/94

02/03/94

XE 12-84

7641271

7

308

ACCESSORIES

W/STUDS

SCOPE BASE

L/REAR SIGHT

FROM:

SHIP TO:

KERPER, ALBERT
1001 PROSS RD
LANDSDALE

PA 19446

KERPER, ALBERT
1001 PROSS RD
LANDSDALE

PA 19446

CUST NO: 091848 C.T.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

059001

WRITE ☐

PROM. DATE

ESTIMATED

VIA

3-15-94

UPS

GUN CONDITION

☐ NEW

☒ LIGHTLY WORN

☐ WORN

☐ VERY WORN

☐ UNREPAIRABLE

☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

D3

METAL

C2

MAIN FAULT

Upon receipt, the rifle is inspected. Inspection revealed that the trigger stop screw and rear engagement screw, which has been provided and is located outside the firing. Also noted was that the trigger spring was repaired to insure safety to the rifle. The rifle is now ready for use.

PARTS

COMMENTS

Replaces trigger assembly and is test rifle as per spec. of gun.

John Smith

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1