

4240 Rev. 10-75

RECEIVING and ESTIMATE REPORT # 02404

ORDER R 31624

RECEIVED 11-29-79 ESTIMATED 3-4-80 VIA UPS CHARGES MAR 5 1980

FROM Snappy Service Center
1400 Highway 2 East Kalispell, Montana

MODEL and GRADE 600 243WIN SERIAL NO. 71789 DATE CODE OK
GRADE CODE 9-63

FOR COMPUTER REFER. ONLY

REPAIR CHG. R W3

MS. 11-66
PARCEL POST W.O. 51085

GUN CONDITION (New) (Slightly worn) (Very worn) (Misused) (Quota) TOTAL

CUSTOMER'S COMPLAINT Gun fired with bolt was open.

MAIN FAULT Chamber rusty - Bolt rusty.

GALLERY REPORT

9/4/69 - Trigger housing open

Pokil Chamber

week done

Repairman *[Signature]*

MAR 1 1980