

RECEIVING AND ESTIMATING REPORT							
COMMENTS							
INITIAL JJM	CUSTOMER ORDER NO.						
DATE RECEIVED 02/13/89	DATE OPENED 02/27/89	DATE CODE AW 3-72	SERIAL NUMBER 6539387	MODEL AND GRADE 700 243 BDL		ORDER R 89-07378	
ACCESSORIES W/STUDS		SCOPE BASE <i>stock cracked</i>		L/SIGHTS			
FROM: RICHARD VERARDI 456 DECATUR AVE STATEN ISLAND NY 10314				SHIP TO: RICHARD VERARDI 456 DECATUR AVE STATEN ISLAND NY 10314			
ACCOUNT NUMBER		ACCOUNT NUMBER N/C		WRITE <input type="checkbox"/>		PROM. DATE	ESTIMATED
						VIA UPS	
<p>DEAR CUSTOMER: WE ARE RIGHT IN THE MIDDLE OF OUR MOST BUSY TIME OF THE YEAR IN SERVICING GUN RETURNS FROM ACROSS THE USA AND CANADA. IF OUR REPAIR TURNAROUND TIME IS A BIT LONGER THAN USUAL, IT IS BECAUSE WE WILL NEVER CUT CORNERS JUST TO RUSH THE GUN BACK TO YOU. WE ALWAYS STRIVE TO GIVE YOU A QUALITY REPAIR IN COMBINATION WITH AS TIMELY A GUN RETURN AS POSSIBLE. SO PLEASE BEAR WITH US AND THANK YOU FOR YOUR SUPPORT.</p>							
REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL		
GUN CONDITION: <input type="checkbox"/> NEW <input type="checkbox"/> SLIGHTLY WORN <input type="checkbox"/> VERY WORN <input type="checkbox"/> MISUSED <input type="checkbox"/> MARRED							
CUSTOMER'S REQUEST							
MAIN FAULT							
PARTS							
REPAIRMAN							
PROOF							
CLEAN							
TEST							
TARGET							
PATTERN							
GALLERY TESTER							
DATE							
DATE							
DATE							
DATE							

ID0925 REV. 6/88