RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL	CUSTOMER ORDER NO.
JJM	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE		ORDER
05/01/89	05/04/89	BH 1-87	B6844094	700 22-250	ADL	R 89-13724

ACCESSORIES W/STUDS SCOPE MNTS SCOPE BASE

FROM:
MARK YODER
RT 2 - COUNTY RD 1100
BOX 225
NAPPANEE IN 46550

SHIP TO:
MARK YODER
RT 2 - COUNTY RD 1100
BOX 225
NAPPANEE IN
46550

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
					UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST Misfired when putting Safety off

MAIN FAULT

PARTS

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
RBL					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 6/88

PRINTED BY THE STANDARD REGISTER COMPANY, U.S.A. STANSET - 9