#### **BARBER - Kinzer PPS GAL RE 0011303**

Remington Arms Co., Inc. **Product Service** Legal Case #:4833

Case Information

RE# Date Opened(PS) **Date Opened Date Closed Incident Date** Pre Lit Lit Obsolete

209308 11/4/2010 10/25/2010 11/5/2010

Customer Information

Type **Business First Name** Last Name Street City Contact State Zip Age 1736 Niblick-Ave. Incident Donald E. Lenig Lancaster PA 17602 H 717-394-9036

Incident Information

Repair Medical Medical Claims Codes Est. Status Treatment

ΡI

PD Altered Adjustments or Cause:4006

Components Unknown S

Concern: 1007 Fired on Safe Release FSR about 20 years C

10/22/10: Customer called into call center. Eric A. sent me an email. Customer stated he had FSR about 20 years ago & wants gun looked at. df

Firearm Information

Mfg. Remington

Type CF/BA

Model/Ga. 700/7MM REM MA SKU n/a

Bbl. Serial DOM

**Date Purchased** 

Where Purchased JERRY OLYPHANT PA Accessories

Original Owner Y

6765432 WY 8/1/1974

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims

Release Date

Reimbursement Settlement

Reim. Date APV

Cash Date APV

Per Ilion - Quote to repair under BLM program

Repair/Replacement Repair/Replacement

Cost

Date

\$45.23

11/10/2010

10/25/10: Sending ARS, letter, & form. df 11/10/10: I spoke w/customer. He does not agree w/quote but asked me to mail it to

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	
	Examiner		B.TRAVIS	
Examination	Exam Date		11/5/2010	
	Product Type		RF	
	Action Type		A	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4833&Type=Case

11/10/2010

PrintDisplay 1 age 2 of 2

	Assigned To		F.SUPRY
Cause	4006	Altered Adjustments or Components	
	Description	•	24" 7MM REM MAG
•	Date Code		WY
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		•
	Muzzle/Crown Condition	Slightly Wom; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face ·	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	.008
	Notch	Slightly Wom; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
	Condition	Slightly Worn; Not Functioning	WILL FOLLOW DOWN
Trigger	Pull	Select	2.5#
	Altered	True	SET SCREWS ALTERED DIRTY/STICKY
	Sub-Assembly	M/700 Bolt Lock	

#### QUOTATION

жишидин иш синрану, ин.

BARBER - Kinzer PPS GAL RE 001130570 Remington Dr. P.O. Box 700 Madison, NC 27025-0700

Parts/Repairs Fax

800-243-9700 336-548-7801

www.remington.com info@remington.com

# **ESTIMATING**

# ALL PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (4) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 15 DAYS, WE SHALL RETURN THE ITEM(S) AS RECEIVED POSTAGE DUE.

Repair Order No	umber	Description/Serial Nu	mber		Date R	eceived -	11/4/2010
RE00209308		6765432				te Date -	11/5/2010
Account # - R-					Curren	t Date -	11/10/2010
Customer				Return T	0		
DONALD E L	ENIG			DONAL		[G	
1736 NIBLIC				1736 NIE			
LANCASTER	L PA 17602 US			LANCAS	STER. PA	17602 U	JS
Phone (H) (	717)-394-9036		Fax Email				
( Trong ( V/ )		·					
Please Circle One							
	EX DISCOVER Card No.			Exp.	Date		
		Ti T. O-11		0	A4 D		
Approval: Custo	mer Signature	Time To Call		Оре	:п Ассі. <u>К</u>	Data	
	sire Any Change Please Use T	ha Davarra Sida Ear V	un Commente	And Manie T	hio Dan	Date_	
		ne Reverse Side For Yo ice: We process checks elec			nis Box		
The second secon		Proble	me Salar	PASA STAR			
Reported		Proble	Found				
I .	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7		• <del></del> • * • • • •	W3	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	2 m 1 m 1 m 1 m 1 m 1 m 1 m 1 m 1 m 1 m	
M123	FORWARD TO PRODUC	CT SERVICE	M123	FORV	VARD TO	PRODUC	Γ SERVICE F
	FOR INSPECTIO	İ					
					·		
		Technician's C	omments	77 July 10 77 / 1			
ProblemNotes	will follow down.trigger						
Probleminoles	assm,clean and test fire u				ok over,rep	nace u igger	piate
	assin, crean and test me t	ilider bott tock progra	III 101 \$20.0	,			
		to a company to the second of the second				***********	
1 "	Estimate **C.O.D./S	hipping and Handling	Charges are	NOT Includ	ed in this (	Quote	
Material #	Material Description		<u>Oty</u>	Warranty	Price/	Discount	Extended
Bowt				<u>Y/N</u>	<u>Unit</u>	<u>Percent</u>	<u>Amt</u>
Part	V እለል ከህ ከበረነ ማሰስ ጥባነር ል	CCD BILDLACV (A	1	Y	\$94.00	00/	<b>#</b> 0.00
Service	X-MARK PRO 700 TRIG A	.338 KM BLACK (U	1	ĭ	<b>⊅94.00</b>	0%	\$0.00
	GR-SHIPPING & HANDLI	NG (GIIN PEDAID)	1	N	\$17.00	0%	\$17.00
]	GR-LABOR	NO (OUN REPAIR)	1	N	\$20.00	0%	\$17.00 \$20.00
	GR-TEST		l	Y	\$20.00	0%	\$20.00
1000117	J. L.		•	•	•		******
					Sub Total	:	\$37.00

\$2.22

\$39.22

Est. Sales Tax:

**Grand Total:** 

frmREInquiry - Repair Inquiry		
Repair Number: RE00209308   Senat 6765432, Model 700	Center Fire Caliber 7 Repairment Bruce Travis	
Verity Repair	Stetus ApproveHdid 1175/2010 11:51:52.7	
ADDRESS INFORMATION  Customer   G. Rec	erved from Return To	
Name: DONALD E LENIG Address 1: 1736 NIBLICK AVE	DONALD E LENIG 1735 NIBLICK AVE	
Address 2 PD Box	PD Box ( gray)	
City   LANCASTER   State:   PA   Zip Code   17502   Countity   US	LANCASTER PA Zip Code: 17602 Country: US	
NA CONTRACTOR OF THE PROPERTY	·m. ·	
Confact / Condition   Problems   Estimate   History / Status   Shipping	/Bding	
Date Code UserID Desci	Oesic2   ▲   □ Shipping Hold   Current Status   ApprovaHold   ApprovaHold	
11/5/2010 9:1 Maint Travisbw Repair Maintenanc	Blatus: F.     Interface Hold   11/5/2010 11:51:52 AM	
11/5/2010 11: Estimate Travisbw Estimate Update 11/5/2010 11: ApprovalH System Immediate SAP Allo	Status: A Parts Received ApproveRack	
11/5/2010 12 Expedite pencer! From Repeir Bench		
11/5/2010 3:3   ApprovalH   BatchJob   Quotation Control	☐ Has Been Approved ILN  I Internal Repair Transfer Number	
	F   Exclude TATC	
Repair Search	Rafresh .	lose
	Aug.	
	A CONTRACT TO SERVICE STATE OF THE PROPERTY OF	
		化基金环烷 化多氯化氯基酚医氯磺基酚 医多角皮肤

	国© Nov	ع کے	ا ک د	VI	EN
Щ	NOV	٠.	3	2010	
	Y:	·	· <b></b> .	•	

October 25, 2010

Donald E. Lenig 1736 Niblick Ave. Lancaster, PA 17602 Ph: 717-394-9036

Subject: # 4833

Dear Mr. Lenig,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the boxes with the name "Supry". Fred Supry will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,

D. Fulder Consumer Affairs Administrator Remington, H&R, Marlin Phone: 1-800-243-9700

Fax: 336-548-7872

**36765432** 



will follow do w.w. Trig. is very porty + set screws altered. Check over, replace TPA, clean + xest fire under bott Lock progression Lov \$ 20,00

Q vote

Remington Arms Company, Inc. ● 870 Kemington Drive ● P.O. Box 700 ● Madison, NC 27025 Phone 800-243-9700 • www.remington.com



# Factory Repair Form

Return to Previous Page

NOTE: Please complete and print this form, and then include it with your firearm.  $\ \ \cdot$ 

Model Number: 33644 - 700	Serial Number: 6765432			
Are you the original owner?: 🛛 YES 🔝 NO				
Name: DONALD E LENIC	Date of Purchase: UNKNDWN			
Address (no PO Boxes): 1736 NIBLIC	CKAVE			
City: LANCASTER	State: PA Zip:17602			
Phone (Daytime): 1-717-394-9036	Fax:			
E-mail Address:(if e-mail address is provided, notification	of receipt and shipment will be			
sent)				
E-mail Address:				
I would like to receive future e-mail updates from Rem	aington.			
Please describe your problem and date of occurrence:	:			
GUN DISCHARGED WH WAS DUSHED TO T	IEN SAFETY			
POSITION WITHOUT	PULLING TRIGGER			
DATE UNKNOWN	•			
	र्के इं			
500 characters left				
Ammunition Information:				
Manufacturer: REMINGTON	Type: EXTENDED RANGE			
Other (i.e. bullet weight/type, shot size, powder):				
Handload Information:				
Powder Used:	Powder Weight:			
Case/Hull Used:	Primer Used:			
Bullet Type/Shot Size:	Reloader Used:			
Firearms Care (Cleaning and Lubrication):				
Brand of cleaning solution used: 3 INONE	OIL			
How aften do you clean the bare? (Months or Number of ro	ounds) WHEN USED			
How often do you clean the action? (Months or Number of	rounds) WHEN USED			
How often do you clean the trigger assembly? (Months or Number of rounds) しい サービッド				
Brand of lubricant used: 3 IN ONE OIL				
How often do you lubricate the bore? (Months or Number of rounds) レルモハ リジミン				
How often do you lubricate the action? (Months or Number of rounds) WHEN USED				

http://www.remington.com/support/repair\_services/factory\_repair\_form.asp

11/24/2009

# BARBER - Kinzer PPS GAL RE 0011309

How often do you lubricate the trigger assembly? (Months or Number of rounds) WHEN USED
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? YES NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?) NEVER
What were the services performed?) NONE
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefier Avenue Ilion, NY 13357
② WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
Record the serial number of your firearm before sending it.     Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)     Remove all accessories from your firearm to prevent loss or damage.     Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.     Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.
Charge repairs will be processed using the following guidelines:
:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)
:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express. Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

© 2009 Remington Arms Company, Inc. All Rights Reserved. Investor Relations | Other Remington Brand Products | Legal Notices | About Us

	3
Other Sites	ł



http://www.remington.com/support/repair\_services/factory\_repair\_form.asp

11/24/2009

# BARBER - Kinzer PPS GAL RE 0011310

# Fulcher, Dell Marie

From:

Aliff, William

Sent: To: Friday, October 22, 2010 4:52 PM Mitchell, Christy; Fulcher, Dell Marie

Subject:

700 SN 6765432

Dell/ Christy

Just spoke to this fellow. Says he had a fire on safety release about 20 years ago and would like to have his gun looked at.

700 in 7mm mag SN 6765432

Donald E Lenig 1736 Niblick Ave Lancaster, PA 17602

717-394-9036

Sincerely,

Eric Aliff | Senior CSR Remington Arms Company, Inc.

870 Remington Dr., PO Box 700, Madison, NC 27025-0700

Phone: 800.243.9700 x8723 | Fax: 336.548.7801

### Freedom Group Family of Companies

Remington | Bushmaster Firearms | DPMS / Panther Arms | Marlin | H&R | Dakota Arms Parker Gun | L.C. Smith | EOTAC | INTC | Advanced Armament Corp | Barnes Bullets

Confidentiality/Proprietary Note: This e-mail and any files transmitted with it are intended solely for the use of the individual or entity to which they are addressed. If you are not the intended recipient or the person responsible for delivering the e-mail to the intended recipient, be advised that you have received this e-mail in error and that any use, dissemination, forwarding, printing or copying of this e-mail is strictly prohibited. If you have received this e-mail in error, please reply back to sender advising that you have received the e-mail in error and delete this e-mail from your system. Thank you.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

# ARS LABEL REQUEST FORM

DATE:		10/25/2010	REQUESTED BY:	Dell
QUANTITY:		1	WEIGHT PER PACK	A(10 lbs
PLEASE GHECKIONE MEDIA COORDINATOR TO MAIL			   WILL MAIL 	xxxxx
DESCRIPTION:	Ref# 4833 Rifle			

# LABEL INFORMATION

MAIL LABEL TO: Donald E. Lenig
1736 Niblick Ave.
Lancaster, PA 17602
Ph: 717-394-9036

RETURN ITEM TC Remington Arms
Attn: Product Service
Ilion, NY

### PLEASE COMPLETE ALL PARTIS OF THIS FORM, AND SEND TO THE MEDIA COORDINATION.

ALL CURR USD 1 OF 1 OCT 25, 2010 ALL CUR ACT UT 10.0 LBS 4XX596 SVC GNDCOM ACT UT
TRACKINGH 1Z4XX5969667397012 REF 1:DONALD E LENIG/CD/DMF REF 2:4833/RIFLE HANDLING CHARGE 0.00 SVC T/P USD SINGLE-PIECE PUB RATE CHRGS RS 0.50 DV 0.00 DC 0.00 AH 0.00 COD 0.00 DGD Ø 00 SD 0.00 SP 0.00 7.45 0.00 PR PUB+HANDLING TOT PUB CHG 7.45







