

Images- Remington M/710 300 Win Mag s/n 71234502

8/3/05

Image #: Burrs in chamber as seen using 90 deg. Borescope. These burrs are approx. 1/4"-3/8" from the belt cut in the chamber located at about the 11:00 o'clock position.

