


VISUAL INSPECTIONS

A-18

3" Crack in tip.



Heavy scratches
on some strokes.