


VISUAL INSPECTION

A-23

Scratch on Stock
Reinforcement Pin.



Lock of Stain.

