

Can you give me an update on the status of this request? The test lab has broken 12 of these during drop testing and are in need of these as soon as possible to continue testing.

Thanks,

Vince

From: Norton, Vince
Sent: Wednesday, February 16, 2005 8:51 AM
To: Vicars, Gerald
Cc: Reesor, Phillip K.; Franz, Scott
Subject: 710 SHORT INSERT

Gerald,

We are in the middle of T&P on the extruded receiver and are breaking inserts during the drop testing. Can you send us 15 short insert assemblies with the fire control assembled and set? We need these right away if possible to not interrupt testing.

Vincent Norton
Research Engineer

Remington Arms Co.
Research & Development Technology Center
315 West Ring Road
Elizabethtown, KY 42701
(270) 769-7612 (phone)
(270) 737-9576 (fax)

vince.norton@remington.com

Subject to Protective Order - Williams v. Remington

BARBER 5.30.06R0000822

ETE00000411