

Image #: Burrs in chamber as seen using 90 deg. Borescope. These burrs are approx. $\frac{1}{4}$ "- $\frac{3}{8}$ " from the belt cut in the chamber located at about the 11:00 o'clock position.

