

RECEIVING AND ESTIMATING REPORT

H 93-14596

INITIAL JJM	CUSTOMER ORDER NO.		ATTN TOM NAGLE			
DATE RECEIVED 06/30/93	DATE OPENED 07/07/93	DATE CODE RA 1-80	SERIAL NUMBER A3200397	NEW SERIAL NUMBER	MODEL AND GRADE 700 7MMEXP BDL	
ACCESSORIES W/STUDS						

FROM:

Set up file

BALLARD, LYDDAN
HWY 106 EAST
P O BOX 829 - RIO HONDO MARINE
RIO HONDO TX 78583

SHIP TO:

BALLARD, LYDDAN
HWY 106 EAST
P O BOX 829 - RIO HONDO
RIO HONDO TX 78583

CUST NO: 080643 C.O.D.L.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C 059015	WRITE ☐	FROM DATE	ESTIMATED	VIA UPS
----------------	------------------------------	--------------------------------	-----------	-----------	------------

GUN CONDITION	REPAIR CHARGE
☒ NEW	EXCISE
☐ LIGHTLY WORN	TAX
☐ WORN	INSURANCE
☐ VERY WORN	UPS
☐ UNREPAIRABLE	PARCEL POST
☐ MARRED	TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	<i>finer when bolt was closed</i>				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Upon receipt could not duplicate customer concern. However, examination revealed very heavy sticky gummy substance on action and trigger assembly. Bolt stop screw not retreating, trigger bar in movement.

PARTS	COMMENTS
<i>Called customer 7/3/93 and reviewed our findings. He stated wife was purchased new 5yr ago. Only used for coast observation. Trigger pull 6 1/4 lbs. San left 012.</i>	<i>Up to clean action and replace trigger assembly complete at 1/4 in. No question of good work.</i>
REPAIRMAN <i>HJB</i>	PROOF
GALLERY REGISTER	DATE
CLEAN ☒	TEST ☒
DATE	DATE
DATE	DATE
DATE	DATE

OFFICE COPY

FD6925 RE

PPS 00311