

RECEIVING and ESTIMATE REPORT

ORDER R 19506

DATE 30-91 ESTIMATED 9/11/81 VIA WP CHARGES

FROM H. G. BENTLIN

2646 JACKSON DR. FALLS CHURCH, VA.

ONE GRADE 700 243 SERIAL NO 223209 DATE ON

BDL GRADE CODE 100 7-66

IMPUTER CODE, DAY W SCOPE BASE PEP ME CNO.

PER. 30.00

PAPER POST WP

ORIENTATION: (North) ✓ (Slightly North) (Very North) (Midwest) (South) TOTAL WP

USER'S COMPLAINT Fires when safe is released. differs

as safety cam sticks in down

position, because of accumulation of dirt

oil.

GALLERY REPORT

Roman excessive oil
and dist from fire
control and strength

Send instruction
folded.

Winkler

SEP 17 1981