

RECEIVING AND ESTIMATING REPORT

CUST NO: 020626 C.O.D		COMMENTS	
TIAL	CUSTOMER ORDER NO.		
JM			
TE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER
8/21/91	08/23/91	BZ 1-75	6829623
MODEL AND GRADE		ORDER	
700 22-250 BDL		R 91-16576	
CESSORIES		W/STUDS SCOPE BASE	
		L/REAR SIGHT	

FROM:	SHIP TO:
BIG JOHN'S GUNS & SUPPLIES 1508 HOUSTON NEDERLAND TX 77627 USA	BIG JOHN'S GUNS & SUPPLIES 1508 HOUSTON NEDERLAND TX USA 77627

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
						UPS

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

UN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

STOMER'S REQUEST: *Fires when closing bolt & also, complaining of headspace problem*

IN FAULT: *Cannot duplicate fire on closing complaint. However, trigger assembly has been improperly adjusted outside factory, as evidenced by non-Remington sealant on adjustment screws - 1) insufficient overtravel 2) insufficient seal engagement. Trigger pull 4 1/2 lbs. semi-lift 20075"*

RTS: *1) check for headspace
2) Send repair quote for new trigger assembly at 1/2 normal cost, as gesture of good-will*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90

PPS 00478