

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-17046

INITIAL CUSTOMER ORDER NO.

ATTN JACK KAST

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

05/27/94

05/31/94

EJ 10-89

C6449486

700

338WIN

MAG/BDL

ACCESSORIES

FROM:

SHIP TO:

CASTRO VALLEY GUN SHOP
22287 REDWOOD RD
CASTRO VALLEY

CA 94546

CASTRO VALLEY GUN SHOP
22287 REDWOOD RD
CASTRO VALLEY

CA
94546

CUST NO:000278 ILION

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

059015

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW

☒ LIGHTLY WORN

☐ WORN

☐ VERY WORN

☐ UNREPAIRABLE

☒ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

R1

TRIGGER GROUP

E

E1

F1

BOLT ASSY.

B3

E2

F2

BARREL ASSY.

B4

D1

E3

F3

REC. ASSY.

B5

D2

E4

F4

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

*Mfg. 10-89 I make to duplicate customer concern as rec'd.
Trigger pull has creep, bolt stop sticks, rear has
gummy residue on its sides as well as the trigger housing.
Metal parts only require a light film of light oil. Exchange
at no charge due to creep in trigger pull.*

ARTS

COMMENTS

*Trigger pull measured 4 1/4 to 4 1/2
lbs as rec'd. rear lift arm .017*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PPS 00972