

FTT - 67 079
449

F.I. YES GUN EXAMINATION REPORT NUMBER: 37 MODEL: 700 BDL L.H.
GENERAL CONDITION: SLIGHTLY WORN R #: 28088
OUTSIDE WORK: SCOPE MOUNTED DATE: 11-22-82
FIRED AMMO TYPE: UNKNOWN FROM: CANTON LIND CO.
& CONDITION: --- 908 Tenth & Commerce St.
Suite 350
Houston, TX 77024
PROOF: R.E.P. 2 INSP.: 123 TEST: 63 GUN #: 6859417
HEADING: O.K. CODE: 5-76
BREACH OPENING: O.K. GA./CAL.: .270 WIN.
RECOIL SHOULDERS: O.K. CHECKED BY: SAW
CHAMBER: O.K. APPROVED: PAH 12/18/82
TEST: --- APPROVED: W 12/18/82
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: PAH 12/23/82
APPROVED: W 12-23-82

COMPLAINT: "... Rifle Fired When I Was Trying To Unload It..."

INCIDENT: MOVED THE SAFETY TO THE OFF POSITION
TO OPEN THE BOLT.

COMMENTS: Replace fire control as requested by
customer.