

RECEIVING AND ESTIMATING REPORT

COMMENTS: **CALL TAG DSV** ORDER R 94-15666

INITIAL: **FPS** CUSTOMER ORDER NO. **05/12/94** DATE RECEIVED **05/12/94** DATE OPENED **EO 10-77** DATE CODE **MS 39328** SERIAL NUMBER **700 243 WIN ADL** MODEL AND GRADE

ACCESSORIES: **L/STUDS**

FROM: **CUMBERLAND, RAYMOND RT 4 BOX 184 DE KALB MS 39328** SHIP TO: **CUMBERLAND, RAYMOND RT 4 BOX 184 DE KALB MS 39328**

CUST NO: 097290 C.L.O.D.

ACCOUNT NUMBER: **068113** ACCOUNT NUMBER INC:  PROM. DATE: ESTIMATED: VIA: **UPS**

GUN CONDITION:  NEW  LIGHTLY WORN  WORN  VERY WORN  UNREPAIRABLE  MARRED

REPAIR CHARGE: **20.00**  
 EXCISE:   
 TAX:   
 INSURANCE:   
 UPS: **8.00**  
 PARCEL POST:   
 TOTAL: **28.00**

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		<i>No correspondence</i>			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: *Apr 10-77 Trigger pull below factory spec. as received. Trigger adjustment screws have been altered outside of the factory. We do not recommend that the trigger be adjusted outside the factory. Exchange Trigger Assy. strictly as a gesture of good will at a special price.*

PARTS: *Trigger Assy Complete* COMMENTS: *Trigger pull measured 2 to 2 1/4 lbs as per spec. lift was OK.*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

*Hand Copy*