



REMINGTON GUN AND/OR TRAP REPAIR INVOICE

REMINGTON ARMS CO., INC. BRIDGEPORT, CONN. 06602

Remington Recommended Repair Facility

Name Belac Gunsmithing
Street 9196 Belac Ave
City Westminster State CA Zip 92683

Customer's Name James R. Harwood
Street 1184 Cliff Dr.
City Laguna Beach State CA Zip _____

Date Firearm or Trap Received

Date Returned to Customer

Returned to Factory

7/7/79

7/12/79

Date

Via

Gun Model

700

Cal. or Gauge

7MM-06

Grade

Barrel Code

Serial Number

A 6693633 RQ

Trap Model

Counter #

Serial Number

Trap

Skeet

Complete Description of Customer's Complaint

Install Gas F 32.5 Blk some run all
Trigger jkt. Take out a sep tighten trigger halt
seem to slightly bind when closing.

Repairs Performed - Describe in detail

Removed jagged edge of front
halt when locking breech travel
Polish tip of cocking piece
Test fire

Repair Charge Breakdown

Parts \$ _____
Labor 7.50
Test Ammunition 2.50
Testing Targets _____
Packing _____
Transportation _____
Total \$ 10.00

DISBURSEMENT
JAN 18 1980
AUDIT

Arms Service (2)
REMINGTON ARMS CO., INC.
ILION, N.Y. 13357

J. J. Smith

SEP 17 1979

Date: 8/28/79