


RECEIVING AND ESTIMATING REPORT

#39

INITIAL		CUSTOMER ORDER NO.		COMMENTS	
JIM		4633		ATTN J KAST EMP 8177-8832	
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
11/29/80	12/01/79	AT-3-88	7649569	7.62MM08	R 98-31837
ACCESSORIES: W/STUDS SCOPE BASE					

FROM:	SHIP TO:
FLANSBURG, SCOTT MAIN STREET POLAND NY 13431	FLANSBURG, SCOTT MAIN STREET POLAND 13431 NY

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
						DOOR



REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION: NEW SLIGHTLY WORN VERY WORN MISUSED MARRED

CUSTOMER'S REQUEST: *"Fired when took safe off, twice, when it was cold"*

MAIN FAULT: *Tuggin assembly rusted from unknown source. Internal tuggin parts not moving freely.*

PARTS: *Replace tuggin assembly at no-charge as gesture of good-will.*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE