

RECEIVING AND ESTIMATING REPORT

COMMENTS

ATT DICK ST JOHN/L REAR SIGHT

INITIAL # B	CUSTOMER ORDER NO. 1338								
DATE RECEIVED 01/09/89	DATE OPENED 01/18/89	DATE CODE CA 4-80	SERIAL NUMBER B6203109	MODEL AND GRADE 700 300	BDL/MAG	ORDER R	89-02258		
ACCESSORIES W/STUDS		SCOPE BASE							

FROM: WILLIAMSON-PATE GUNSMITH SERVI DBA/GUNCRAFT, INC (PRO 117 W PIPELINE ROAD HURST, TEXAS 000076053	SHIP TO: WILLIAMSON-PATE GUNSMITH SERVI DBA/GUNCRAFT, INC (PRO 117 W PIPELINE ROAD HURST, TEXAS 000076053
--	---

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	FROM DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	-----------	-----------	------------

DEAR CUSTOMER:
 WE ARE RIGHT IN THE MIDDLE OF OUR MOST BUSY TIME OF THE YEAR IN SERVICING GUN RETURNS FROM ACROSS THE USA AND CANADA. IF OUR REPAIR TURNAROUND TIME IS A BIT LONGER THAN USUAL, IT IS BECAUSE WE WILL NEVER CUT CORNERS JUST TO RUSH THE GUN BACK TO YOU. WE ALWAYS STRIVE TO GIVE YOU A QUALITY REPAIR IN COMBINATION WITH AS TIMELY A GUN RETURN AS POSSIBLE. SO PLEASE BEAR WITH US AND THANK YOU FOR YOUR SUPPORT.

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: NEW SLIGHTLY WORN VERY WORN MISUSED MARRED

CUSTOMER'S REQUEST

MAIN FAULT

PARTS

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

BD0923 REV. 4/88

OFFICE COPY