

|               |             |           |               |                   |                 |
|---------------|-------------|-----------|---------------|-------------------|-----------------|
| L/CLIP        |             |           |               |                   |                 |
| RECEIVED      | DATE OPENED | DATE CODE | SERIAL NUMBER | NEW SERIAL NUMBER | MODEL AND GRADE |
| 1/93          | 05/12/93    | WZ 8-75   | A6061221      |                   | 788 243 WIN     |
| ORIG: W/STUDS |             |           |               |                   |                 |

*Stupella*

*K.F. Sperry*

GAPEN GUN SALES  
608 COLLEGE STREET  
BARRACKVILLE

WV 26559

SHIP TO:  
GAPEN GUN SALES  
608 COLLEGE STREET  
BARRACKVILLE WV 26559

CUST NO: 079070 C.O.D

|              |                    |                                |            |           |                            |
|--------------|--------------------|--------------------------------|------------|-----------|----------------------------|
| ITEM NUMBER  | ACCOUNT NUMBER /VC | WRITE <input type="checkbox"/> | PROM. DATE | ESTIMATED | VIA<br>UPS                 |
| CONDITION    |                    |                                |            |           | REPAIR CHARGE <i>20.00</i> |
| REPAIR GROUP |                    |                                |            |           | EXCISE                     |
| REPAIR PARTS |                    |                                |            |           | TAX                        |
| REPAIR WORK  |                    |                                |            |           | INSURANCE                  |
| REPAIR COST  |                    |                                |            |           | UPS                        |
| REPAIR TOTAL |                    |                                |            |           | PARCEL POST                |
|              |                    |                                |            |           | TOTAL                      |

| REPAIR CONCERN | AMMO | FUNCTION | FINISH | ACCURACY | FIT | INSPECT |
|----------------|------|----------|--------|----------|-----|---------|
|                | A1   | B1       |        |          |     |         |
| REPAIR GROUP   |      | B2       |        |          | E1  | F1      |
| REPAIR PARTS   |      | B3       |        |          | E2  | F2      |
| REPAIR WORK    |      | B4       |        |          | E3  | F3      |
| REPAIR COST    |      | B5       |        | D2       | E4  | F4      |
|                |      |          | C1     | D3       | E5  | F5      |
|                |      |          | C2     |          |     |         |

ULT *Upon receipt trigger assembly housing bad, has been removed  
to the factory. Saw out trigger, being careful not to damage  
trigger housing. Trigger spring not in installed position.*

|  |       |                                     |                                     |        |         |
|--|-------|-------------------------------------|-------------------------------------|--------|---------|
| COMMENTS   |       |                                     |                                     |        |         |
| <i>Replace trigger assembly complete<br/>&amp; clean action at 1/2 normal cost</i> |       |                                     |                                     |        |         |
| REPAIRMAN  | PROOF | CLEAN                               | TEST                                | TARGET | PATTERN |
|  |       | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |        |         |
| GALLERY TESTER   | DATE  | DATE                                | DATE                                | DATE   | DATE    |
|  |       |                                     |                                     |        |         |

OFFICE COPY

RD6925 REV. 1/92