

RECEIVING AND ESTIMATING REPORT

 COMMENTS *to Product Service.*
 W/TASCO 6-18X40 SCOPE

 ORDER
 R 93-13732

INITIAL	CUSTOMER ORDER NO.		DATE RECEIVED		DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE	
PS	00518		16/14/93		06/17/93	XI 12-88	A6392071		700	22-250 BDL
ACCESSORIES			SCOPE MNTS			SCOPE BASE			L/REAR SIGHT	
W/STUDS										

FROM:

 J D ENTERPRISES
 18 JORDAN MILL COURT
 WHITE HALL

MD 21161

SHIP TO:

 J D ENTERPRISES
 18 JORDAN MILL COURT
 WHITE HALL

MD 21161

CUST NO: 055943 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
					UPS
GUN CONDITION					REPAIR CHARGE <i>25.00</i>
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED					EXCISE TAX INSURANCE UPS PARCEL POST TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
RIGGER GROUP		B2				
BOLT ASSY.		B3			E2	
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

*Upon receipt of gun in operation, found gun was not in
 order. Upon inspection revealed that the receiver has been removed from
 the trigger adjustment & trigger was loose, indicating that no adjustment
 had been made since the factory. Sept. 1988*

PARTS

Gun needs cleaning

COMMENTS

*Receiver trigger assembly, compact
 at 1/2 normal replacement cost as
 evidence of good work & clean action*

Go ahead

Return with scope

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
<i>PS</i>		☒	☒		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92