

RECEIVING AND ESTIMATING REPORT

ORDER
R 93-00032

INITIAL CUSTOMER ORDER NO.

J.M.

DATE RECEIVED

12/23/92

DATE OPENED

01/04/93

DATE CODE

DS 7-69

SERIAL NUMBER

6262897

NEW SERIAL NUMBER

MODEL AND GRADE

700

22-250

ADL

ACCESSORIES

SCOPE BASE

L/SIGHTS

FROM:

KEEGAN, KENNETH
HWC 3 BOX 24
MARTIN

SD 57551

SHIP TO:

KEEGAN, KENNETH
HWC 3 BOX 24
MARTINSD
57551

CUST NO: 072694 C.O.D.L.

ACCOUNT NUMBER

ACCOUNT NUMBER W/C

WRITE ☐

CLEAN/TEST

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

OLT ASSY.

B3

ARREL ASSY.

B4

EC. ASSY.

B5

OOD

C1

D3

ETAL

C2

D2

D3

IN FAULT

Stk cracked along grace by butt

Unable to duplicate Customer's Concerns

However, inspection revealed that the trigger assembly adjustment screws have been tampered with without the factory.

RTS Trigger Pull 3.75 lbs.

San test .0045

COMMENTS

Stk is repairable.

Repaired trigger assembly complete
at 1/2 normal cost. as per test of good
will

Fixed Pull

REPAIRMAN
FB.

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/82

PPS 02680