

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product
Service

ORDER

R 94-04359

INITIAL CUSTOMER ORDER NO.

JJM

BOTTOM HALF OF MOUNTS ONLY

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
02/02/94	02/03/94	XE 12-84	7641271		7 308

ACCESSORIES W/STUDS SCOPE BASE
L/REAR SIGHT

FROM:

KERPER, ALBERT
1001 PROSS RD
LANDSDALE

PA 19446

SHIP TO:

KERPER, ALBERT
1001 PROSS RD
LANDSDALE

PA

19446

CUST NO: 091848 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

059001

WRITE ☐

FROM DATE

ESTIMATED

VIA

3-15-94

UPS

GUN CONDITION

- ☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
------------------	------	----------	--------	----------	-----	---------

CYCLE

A1

B1

TRIGGER GROUP

B2

E1

F1

BOLT ASSY.

B3

E2

F2

BARREL ASSY.

B4

D1

E3

F3

REC. ASSY.

B5

D2

E4

F4

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

Upon receipt, the rifle is inspected. Inspection revealed that the trigger stop screw and rear engagement screw, which has been produced and is adjusted within the factory. Also noted was that more than normal force is required to move safety to the on/off position.

PARTS

COMMENTS

Replaces trigger assembly and is set into regulator of gun unit.

Goodman

RECEIVED

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1

PPS 02717