

RECEIPT AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-16371

TIAL CUSTOMER ORDER NO.
DC

ATTN: JACK KAST
STOCK NOT OF REM. MAN.

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
05/20/94	05/20/94	BZ 1/75	6711465		700 222REM.
ACCESSORIES	W/STUDS	SCOPE MNTS	SCOPE BASE		

DM: KNIGHT, BRYCE
7419 HARRIS
RAYTOWN MO 64133

SHIP TO: KNIGHT, BRYCE
7419 HARRIS
RAYTOWN MO 64133

CUST NO: 097644 C.O.D.

COUNT NUMBER	ACCOUNT NUMBER N/C	PROM. DATE	ESTIMATED	VIA
263103				UPS
CONDITION	REPAIR CHARGE			20.00
NEW	EXCISE			
LIGHTLY WORN	TAX			
WORN	INSURANCE			
VERY WORN	UPS			5.00
UNREPAIRABLE	PARCEL POST			
MARRED	TOTAL			28.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CLE		B1				
TRIGGER GROUP		B2			E1	F1
SLT ASSY.		B3			E2	F2
REL ASSY.		B4		D1	E3	F3
C. ASSY.		B5		D2	E4	F4
TRIGGER			C1	D3	E5	F5
TOTAL			C2			

Manufacturer's 1-75 firing pin follows down when bolt is closed properly. All trigger adjusting screws have been checked outside of factory. We do not recommend that the trigger be adjusted outside of the factory. Exchange trigger any. at a special price strictly as a gesture of good will.

REPAIRMAN COMMENTS: *Trigger pull measured 2 to 2 1/4 lbs as reqd. see log case 1003*

Stock not of Remington Mfgs.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94