

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 93-24262

INITIAL JJM	CUSTOMER ORDER NO.					
DATE RECEIVED 11/05/93	DATE OPENED 11/10/93	DATE CODE EE 10-84	SERIAL NUMBER B6631169	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06	RDL/LH
ACCESSORIES W/STUDS		SCOPE BASE				

FROM:

SHIP TO:

LEBANON SPORT CTR INC
74 NORWICH AVE
OLD RT 2 BOX 302
LEBANON

CT 06249

LEBANON SPORT CTR INC
74 NORWICH AVE
OLD RT 2 BOX 302
LEBANON

CT

06249

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

CUST NO: 000514 WITH

PROM. DATE

ESTIMATED

VIA

WRITE ☐

UPS

GUN CONDITION

- ☒ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Upon receipt, unable to diagnose customer concern.
Disassembly revealed a rusty safety contact spring. Rust from
unknown source. Trigger pull measured at 7.5 lbs. More than normal.

PARTS

COMMENTS

Not required to move safety assembly.
Repl. mfg 1984
Repl. complete trigger assembly
at N/C, as per spec & good result

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

PPS 02946