

## RECEIVING AND ESTIMATING REPORT

COMMENTS

Product  
Service

ORDER

R 94-00649

INITIAL CUSTOMER ORDER NO.

W/1 SPENT CASE

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

01/05/94

01/06/94

DJ 9-89

C6441815

700 7MMAG

BDL

ACCESSORIES

W/STUDS

FROM:

SHIP TO:

LEO'S CUSTOM STOCKS  
1767 WASHINGTON AVE  
LIBRARY

PA 15129

LEO'S CUSTOM STOCKS  
1767 WASHINGTON AVE  
LIBRARYPA  
15129

ACCOUNT NUMBER

ACCOUNT NUMBER NYC

CUST NO: 005846 WITH

FROM DATE

ESTIMATED

VIA

WRITE ☐

2-12-94

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

METAL

C2

MAIN FAULT

Upon receipt, could not duplicate customer concern of gun not firing. However, examination of trigger assembly revealed and then unknown source.

PARTS

COMMENTS

1. Replace complete trigger assembly at rate to get gun up and running.

2. Check rifle headspace.

REPAIRMAN

KLB

GALLERY TESTER

PROOF

CLEAN

TEST

TARGET

PATTERN

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6825 REV. 1/92

RPS 02072